## HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN

## TRANSMITTAL SHEET <u>HC-ASB-61-303</u>

#### **Propeller - Cessna 180 Propeller Replacement**

June 26, 2008

This page transmits a revision to Alert Service Bulletin HC-ASB-61-303.

- Original Issue, dated May 19/08
- Revision 1, dated Jun 26/08

Propeller assemblies that have previously complied with the inspections required in a previous revision of this Alert Service Bulletin are not affected by this revision.

FAA approval has been obtained on technical data in this publication that affects type design.

Changes are shown by a change bar in the left margin of the revised pages.

This revision is issued to change the following in the Alert Service Bulletin:

- Modified the Warning statement on page 2

This Alert Service Bulletin is reissued in its entirety.

## HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN

TRANSMITTAL SHEET

<u>HC-ASB-61-303</u>

(This page is intentionally blank.)

### **ALERT SERVICE BULLETIN**

#### HC-ASB-61-303

#### **Propeller - Cessna 180 Propeller Replacement**

#### 1. Planning Information

#### A. Effectivity

- (1) The Cessna 180 (A-H,J,K) Skywagon equipped with floats and Hartzell PHC-(C,G)3YF-1RF/F7691() aluminum hub compact propeller installed in accordance with Hartzell Supplemental Type Certificate (STC) SA00852AT or SA09025SC are affected by this Service Bulletin.
- (2) The Cessna 180 (A-H,J,K) Skywagon that does not have floats installed may continue to use the PHC-(C,G)3YF-1RF/F7691() propeller.

NOTE 1: Supplemental Type Certificate SA00852AT was previously distributed through Bonaire Aviation Company.

#### B. Reason

- (1) The Cessna 180 (A-H,J,K) Skywagon equipped with floats and the Hartzell PHC-(C,G)3YF-1RF/F7691() propeller does not provide the thrust required to achieve the climb performance desired for an aircraft on floats. The Cessna 180 (A-H,J,K) Skywagon without floats installed does not experience this condition.
- (2) Hartzell has received one report of a Cessna 180 (A-H,J,K) Skywagon equipped with floats that experienced a problem with climb performance.
- (3) Replacement of the PHC-(C,G)3YF-1RF/F7691() propeller with the PHC-(C,G)3YF-1RF/F8468A-6R propeller will remove the possibility of this condition.
- (4) Regulatory action is not expected.

#### C. Description

- (1) This Service Bulletin requires replacement of the PHC-(C,G)3YF-1RF/F7691() propeller with the PHC-(C,G)3YF-1RF/F8468A-6R propeller when installed on the Cessna 180 (A-H,J,K) Skywagon equipped with floats.
- (2) This Service Bulletin introduces the PHC-(C,G)3YF-1RF/F8468A-6R propeller for installation on a Cessna 180 (A-H,J,K) Skywagon equipped with floats.

### **ALERT SERVICE BULLETIN**

#### HC-ASB-61-303

#### **Propeller - Cessna 180 Propeller Replacement**

#### D. Compliance

WARNING: FAILURE TO COMPLY WITH THIS ALERT SERVICE BULLELTIN

MAY RESULT IN DEATH, SERIOUS BODILY INJURY, AND/OR

SUBSTANTIAL PROPERTY DAMAGE.

(1) Before next flight, discontinue operation of any Cessna 180 (A-H,J,K) aircraft equipped with floats and with propeller model PHC-(C,G)3YF-1RF/F7691() in accordance with STC SA00852AT or SA09025SC. This propeller model is not approved for operation with floats.

- (2) Before next flight, remove any PHC-(C,G)3YF-1RF/F7691() propeller from the aircraft if the aircraft has floats installed.
- (3) Replace the propeller assembly with a PHC-(C,G)3YF-1RF/F8468A-6R propeller assembly.

NOTE 1: STC SA09025SC has been replaced by STC SA00852AT.

NOTE 2: Hartzell STC's SA00852AT has been amended to permit the installation of Hartzell propeller model PHC-(C,G)3YF-1RF/F8468A-6R on a Cessna 180 (A-H,J,K) aircraft equipped with floats.

#### E. Approval

(1) FAA approval has been obtained on technical data in this publication that affects type design.

#### F. Manpower

- (1) Approximately 2.0 man hours are required for propeller removal and replacement.
- (2) Approximately 3.0 man hours are required for dynamic balance.

### **ALERT SERVICE BULLETIN**

#### HC-ASB-61-303

#### **Propeller - Cessna 180 Propeller Replacement**

#### G. Weight and Balance

- (1) The PHC-C3YF-1RF/F8468A()-6R propeller and spinner assembly are 9.0 lb. (0.45 kg) greater than the PHC-C3YF-1RF/F7691() propeller and spinner assembly.
- (2) The PHC-C3YF-1RF/F8468A()-6R propeller and spinner assembly are 7.8 lb. (4.44 kg) greater than the PHC-G3YF-1RF/F7691() propeller and spinner assembly.
- (3) The PHC-G3YF-1RF/F8468A()-6R propeller and spinner assembly are 10.2 lb. (1.36 kg) less than the PHC-C3YF-1RF/F7691() propeller and spinner assembly.
- (4) The PHC-G3YF-1RF/F8468A( )-6R propeller and spinner assembly are 9.0 lb. (3.63 kg) greater than the PHC-G3YF-1RF/F7691( ) propeller and spinner assembly.

#### H. References

- (1) Hartzell Owner's Manual 115N (61-00-15)
- (2) Hartzell Compact Propeller Overhaul and Maintenance Manual 113B (61-10-13)

#### I. Other Publications Affected

(1) Hartzell Application Guide 159 (61-02-59)

#### 2. Material Information

- A. Material Necessary Propeller Replacement
  - (1) PHC-(C,G)3YF-1RF/F7691() propeller assembly is approved for installation on Cessna 180(A-H,J,K) without floats.
  - (2) PHC-(C,G)3YF-1RF/F8468A-6R propeller assembly is approved for installation on Cessna 180(A-H,J,K) with or without floats.

### ALERT SERVICE BULLETIN

#### HC-ASB-61-303

#### **Propeller - Cessna 180 Propeller Replacement**

#### 3. Accomplishment Instructions

- A. When installed on an aircraft with floats, the Hartzell PHC-(C,G)3YF-1RF propeller must use the F8468A-6R blades. The PHC-(C,G)3YF-1RF/F7691() propeller assembly must be removed and replaced with a PHC-(C,G)3YF-1RF/F8468A-6R propeller assembly.
- B. Propeller replacement
  - (1) Remove the currently installed PHC-(C,G)3YF-1RF/F7691() propeller assembly in accordance with Hartzell Owner's Manual 115N (61-00-15).
  - (2) Install a PHC-(C,G)3YF-1RF/F8468A-6R propeller assembly in accordance with Hartzell Owner's Manual 115N (61-00-15).
- C. Indicate compliance with this Alert Service Bulletin in the propeller logbook.

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

#### 1. Pricing Information

Part Number Keyword Special
Part Number Pricing

PHC-C3YF-1RF/F8468A-6R Propeller Assembly \$6,900.00

#### 2. Eligibility

- A. Only a Cessna 180 (A-H,J,K) Skywagon with floats and with the Hartzell PHC-(C,G)3YF-1RF/F7691() aluminum hub propeller installed in accordance with Hartzell Supplemental Type Certificate (STC) SA00852AT or SA09025SC are eligible for the special pricing provided in this Alert Service Bulletin.
  - (1) The PHC-(C,G)3YF-1RF/F7691() propeller must be returned to Hartzell Propeller Inc.
  - (2) Supplemental Type Certificate SA00852AT was previously distributed through Bonaire Aviation Company.
- B. Special pricing is available until May 31, 2009.

#### 3. Description

- A. Hartzell Alert Service Bulletin HC-ASB-61-303 requires replacement of the currently installed PHC-(C,G)3YF-1RF/F7691() propeller assembly with a PHC-(C,G)3YF-1RF/F8468A-6R propeller assembly, when installed on a Cessna 180 (A-H,J,K) aircraft with floats.
- B. Hartzell will provide special pricing for a PHC-C3YF-1RF/F8468A-6R propeller assembly.

NOTE: Hartzell will provide the PHC-C3YF-1RF/F8468A-6R for the special pricing program. The PHC-G3YF-1RF/F8468A-6R will not be provided for this special pricing.

Propeller Model: PHC-(	C,G)3YF-1RF	Document No.:	HC-ASB-61-303	Revision:	1
Component Part Number	F7691()	Date of Issue:	May 19/08	Rev. Date: .	Jun 26/08

### ALERT SERVICE BULLETIN APPENDIX

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

#### 4. Recommended Repair Facilities

- A. Hartzell has a worldwide network of Recommended Repair Facilities that are approved by Hartzell for overhaul and repair of Hartzell propellers.
- B. Each facility must meet the standard FAA requirements and the additional Hartzell requirements before being approved by Hartzell. Each facility is audited by Hartzell to verify the continuation of the standards.
- C. Hartzell recommends that you use one of these facilities when purchasing a new propeller or having your propeller overhauled or repaired.
- D. Refer to Table 1 for a list of Recommended Repair Facilities. This list is also available on the Hartzell website at www.hartzellprop.com/Product Support/Worldwide Network.

#### 5. Special Pricing Program

- A. Hartzell PHC-(C,G)3YF-1RF/F7691() propellers installed on Cessna 180 (A-H,J,K) with floats are affected by this Alert Service Bulletin.
  - (1) Hartzell will provide a PHC-C3YF-1RF/F8468A-6R propeller assembly for \$6,900.00 USD. Special pricing is available until May 31, 2009.
    - NOTE 1: List price for the F8468A-6R blades is \$3,126.00 USD per blade. List price for a PHC-C3YF-1RF/F8468A-6R propeller assembly is \$13,196.00 USD.
    - NOTE 2: The currently installed spinner assembly may be retained by the owner for use with the PHC-C3YF-1RF/F8468A-6R propeller assembly.
  - (2) Hartzell will provide a copy of the Supplemental Type Certificate SA00852AT.

NOTE 1: STC SA09025SC has been replaced by STC SA00852AT.

NOTE 2: Hartzell STC's SA00852AT has been amended to permit the installation of Hartzell propeller model PHC-(C,G)3YF-1RF/F8468A-6R on a Cessna 180 (A-H,J,K) aircraft equipped with floats.

Propeller Model:	PHC-(C,G)3YF-1RF	Document No.:	HC-ASB-61-303	Revision:	1
Component Part I	Number: F7691()	Date of Issue:	May 19/08	Rev. Date:	Jun 26/08

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

(3) Complete the Propeller Order Form on page 9 for each propeller assembly or aircraft identified in the Effectivity section of Alert Service Bulletin Appendix and fax or mail to:

Hartzell Propeller Inc. Attn.: Product Support One Propeller Place

Piqua, Ohio 45356-2634 USA

Phone: 937.778.4379

Fax: 937.778.4391 (Intl. 001.937.778.4391)

- (4) Hartzell Product Support will contact the facility ordering the propeller assembly with a Return Authorization number to return the unserviceable propeller assembly.
- (5) Hartzell New Part Sales will contact the facility ordering the propeller assembly with an approximate ship date for the new propeller assembly.
- (6) Upon receipt of the new propeller assembly, ship the unserviceable propeller assembly to Hartzell:

Hartzell Propeller Service Center

Attn.: Alert Service Bulletin HC-ASB-61-303 Coordinator

5465 W. State Route 185 Piqua, Ohio 45356-2634 USA

- NOTE 1: Be sure to reference Return Material Authorization Number on the return shipment. Replacement propeller packaging should be used to return exchange propeller.
- NOTE 2: The unserviceable propeller assembly must be received within 30 days of shipment of replacement propeller. The Facility that ordered the replacement propeller will be invoiced for full list price if unserviceable propeller is not returned to Hartzell within the 30 days.

Propeller Model:	PHC-(C	,G)3YF-1RF	Document No.:	HC-ASB-61-303	Revision:	1
Component Part No	umber:	F7691()	Date of Issue:	May 19/08	Rev. Date:	Jun 26/08

# HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN APPENDIX

#### HC-ASBA-61-303

#### Propeller - Cessna 180 Blade Replacement

- B. Hartzell Contact Information
  - (1) Contact information for Hartzell Product Support

Hartzell Propeller Inc. Attn.: Product Support One Propeller Place

Piqua, Ohio 45356-2634 USA

Phone: 937.778.4379

Fax: 937.778.4391 (Intl. 001.937.778.4391)

(2) Contact information for Hartzell New Parts Sales

Hartzell Propeller Inc. Attn.: New Parts Sales One Propeller Place

Piqua, Ohio 45356-2634 USA

Phone: 937.778.4379

Fax: 937.778.4215 (Intl. 001.937.778.4215)

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

#### **Argentina**

Helices Clerici Santa Maria De Oro 3061 1712 Castelar Buenos Aires, Argentina Attn: Hugo Clerici

Phone: 54-11-4623-5754
Fax: 54-11-4661-9761

E-mail: clerici@satlink.com.ar

#### **Australia**

Aircraft Propeller & Spares (Aust.) Pty. Ltd. P. O. Box 200

Mentone, Victoria, Australia 3194

Attn: Linton Hayres Phone: 61-3-9580-2034 Fax: 61-3-9580-0765

After Hours No.: 61-3-9707-2775 E-mail: propbits@ozemail.com.au

Web: www.propbits.com

East Coast Propellers Pty. Ltd. Building 641, Klemm Street

Bankstown Airport

Sydney, New South Wales 2200, Australia

Attn: John Marks Phone: 61-2-9791-0246 Fax: 61-2-9791-0057

E-mail: eastcoastpropellers@bigpond.com.au Web: www.eastcoastpropellers.com.au

West Coast Propellers P/L Unit 6/10 Whyalla Street Willetton, Western Australia 6155 Postal Address:

P. O. Box 3111 Success, Western Australia 6164

Attn: Stephen Ashley Phone: 61-8-9354-4113 Fax: 61-8-9354-4113

Mobile Phone: 0417-945-367 or 0419-049-866 Email: westcoastprops@bigpond.com.au

#### Brazil

Diamond Aviação Ltda Av. Santos Dumont n. 1317 Setor Santa Genoveva 74672-420 Goiâna - GO Brasil Phone: 55 62 515 9900

Fax: 55 62 515 9900 E-mail: diamond@diamondaviacao.com.br

Web: www.diamondaviacao.com.br

#### Canada

Canadian Propeller Ltd. 462 Brooklyn Street Winnipeg, Manitoba R3J 1M7, Canada Attn: Maurice Wills

Phone: 204-832-8679 or 1-800-773-6853

Fax: 204-888-4696

E-mail: info@canadianpropeller.com Web: www.canadianpropeller.com

### Hartzell Recommended Repair Facilities Table 1

## ALERT SERVICE BULLETIN APPENDIX

#### HC-ASBA-61-303

#### Propeller - Cessna 180 Blade Replacement

Hope Aero Propeller & Components, Inc.

2283 Anson Drive

Mississauga, Ontario, Canada L5S 1G6

Attn: Harry Hope

Phone: 905-677-8747 or 800-268-9900

Fax: 905-677-5935

E-mail: propellers@hopeaero.ca

Web: www.hopeaero.com

#### **England**

Proptech

**Nevil Shute Road** 

Portsmouth

Hants PO3 5RX, UK

Attn: Andrew Featherstone, General Manager

Phone: +44 (0)2392 657772 Fax: +44 (0)2392 657771

E-mail: andrew featherstonhaugh@hsaviation.co.uk

Web: www.proptech.info

#### **France**

Technic Aviation
Z. I. Saint Maurice

04100 Manosque, France Attn: Marc Dubois

Phone: 33-492726648 Fax: 33-492878724

E-mail: m.dubois@technicaviation.com

#### Germany

Hoffmann GmbH & Co., KG.

Kupferlingstrasse 9

D-83022 Rosenheim, Germany

Attn: Andrea Huber, Sales & Service Dept. Phone: 49-8031-1878-0 Fax: 49-8031-187878

E-mail: andrea@hoffmann-prop.com Web: www.hoffmann-prop.com

Röder Präzision GmbH

Am Flugplatz

D-63329 Egelsbach, Germany

Repair & Overhaul: Attn: Hans Burger

Tel: +49-(0)6103-4002-600 Fax: +49-(0)6103-4002-236 E-mail: hansburger@rp-eg.com Web: www.roeder-praezision.com

#### **New Zealand**

Safe Air Limited

P. O. Box 244, Blenheim Airport

Blenheim, New Zealand Attn: Steve Guthrie Phone: 64-3-572-7813

Fax: 64-3-572-8846 Mobile Phone: 21-388-767

E-mail: steve.guthrie@safeair.co.nz

Web: www.safeair.co.nz

## Hartzell Recommended Repair Facilities Table 1 (Continued)

Propeller Model: PHC-(C,G)3YF-1RF Document No.: HC-ASB-61-303 Revision: 1

Component Part Number: F7691() Date of Issue: May 19/08 Rev. Date: Jun 26/08

## ALERT SERVICE BULLETIN APPENDIX

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

#### **Norway**

Norronafly PW+AP A/S

P. O. Box 64

N-1330 Oslo Airport, Norway

Attn: Roar Mikalsen Phone: 47-67539066 Fax: 47-67590320

E-mail: prop@norronafly.com Web: www.norronafly.com

#### **Singapore**

C & A Aviation (Pte) Ltd. Buildings 110/143

East Camp, Seletar Airfield, Singapore 798370

Postal Address:

Jalan Kayu Post Office Box 59

Singapore 918002 Attn: K. H. Chui Phone: 65-4812233 Fax: 65-4810827

E-mail: Sales@cnaavia.com.sg

#### **United States**

Aviation Propellers, Inc. 12970 Port Said Road Opa Locka, Florida 33054

Attn: Tom Gaither

Phone: 305-688-9439 or 305-688-6030

Fax: 305-681-4236 E-mail: dwj@avprops.com Web: www.avprops.com Flightcraft Inc.

7777 NE. Airport Way Portland, OR. 97218 Attn: Jeff Howell

Phone: 503-331-4200 or 800-547-9307

Fax: 503-331-4261

E-mail: propshop@flightcraft.com

Web: www.flightcraft.com

Hartzell Service Center

Piqua Airport

5465 West State Route 185

Piqua, Ohio 45356 Attn: Jeff Slattery Phone: 937-778-4201 Fax: 937-778-4202

Service Center: servicecenter@hartzellprop.com

Web: www.hartzellprop.com

Jordan Propeller Service, Inc.

103 East Rhapsody San Antonio, Texas 78216

Attn: Gary Jordan Phone: 210-344-3064 Fax: 210-344-9433

E-mail: Jordprop@Netxpress.com

Maxwell Aircraft Service

Crystal Airport

Minneapolis, Minnesota 55429

Attn: Conrad Maxwell Phone: 763-533-8611 Fax: 763-533-3219

Web: www.hcsweb.com/maxwell

### Hartzell Recommended Repair Facilities Table 1 (Continued)

# HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN APPENDIX

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

Ottosen Propeller & Accessories, Inc.

105 South 28th Street Phoenix, Arizona 85034 Attn: Don Ottosen

Phone: 602-275-8514 or 800-528-7551

Fax: 602-275-8594

E-mail: ottosenprop@uswest.net

Piedmont Aviation Component Services

P. O. Box 525

3817 N. Liberty Street

Winston Salem, North Carolina 27102

Attn: Chuck Johnson Phone: 336-776-6260 Fax: 336-776-6261

Web: www.piedmontaviation.com

## Hartzell Recommended Repair Facilities Table 1 (Continued)

#### HC-ASBA-61-303

#### **Propeller - Cessna 180 Blade Replacement**

<u>Propeller Order Form</u>		
Hartzell Propeller Inc. Phone: 937.778.4379 Fax: 937.778.4391 E-mail: techsupport@hartzellprop.com	(Intl. 001.937.778.4391)	
PO Number (if applicable):		
Currently Installed Propeller Model:		
Propeller or Hub Serial Number:		
Aircraft Registration Number:		
<u>Customer</u> :	Ship To:	
Company:	Company:	
Name:		
Address:		
City:		
State: Zip:		
Country:		
Phone:		
E-mail address:	Fax:	
Do not write below this line:		
Approval Number:		
RMA Number:		
Propeller Model: PHC-(C,G)3YF-1RF Docume	nt No.: HC-ASB-61-303 Revision: 1	
Component Part Number: F7691() Date of	ssue: May 19/08 Rev. Date: Jun 26/0	 8

# HARTZELL PROPELLER INC. ALERT SERVICE BULLETIN APPENDIX

HC-ASBA-61-303

**Propeller - Cessna 180 Blade Replacement** 

(This page is intentionally blank.)