

HARTZELL PROPELLER INC. **SERVICE BULLETIN**

TRANSMITTAL SHEET

HC-SB-61-97A

Propellers - Blade Inspection

April 16, 2007

This page transmits Revision 1 to Service Bulletin HC-SB-61-97A.

- Original Issue, dated May 03/71
- Revised, dated Dec 01/71
- Revision A, dated Mar 01/73
- Revision 1, dated Apr 16/07

Propeller assemblies that have previously complied with this Service Bulletin are not affected.

FAA approval has been obtained on technical data in this publication that affects type design.

Changes are shown by a change bar in the left margin of the revised pages.

This revision is issued to change the following in the Service Bulletin:

- Revised and reissued Service Bulletin - The procedure for inspection and shot peening the blade balance bore has been removed and the user is referred to the Hartzell Aluminum Blade Overhaul Manual 133C (61-13-13).
- The Service Bulletin is being reissued as an alternate method of compliance with Airworthiness Directive 72-08-04.
- Removed requirement to shot peen the blade retention radius of Y shank blades.

(This page is intentionally blank.)

HARTZELL PROPELLER INC.
SERVICE BULLETIN
HC-SB-61-97A
Propellers - Blade Inspection

1. Planning Information

A. Effectivity

- (1) Hartzell T10173() and T10176() aluminum blades used in HC-B3TN-(2,3,5), HC-B3TF-7, and HC-B4TN-3 model propeller assemblies with serial numbers B85886 and lower, except blade serial numbers listed in Table 1, are affected by this Service Bulletin.
- (2) Hartzell T10173() and T10176() aluminum blades used in HC-B3TN-(2,3,5), HC-B3TF-7, and HC-B4TN-3 model propeller assemblies with blade serial numbers B85887 and higher, including serial numbers listed in Table 1, are not affected by this Service Bulletin.
- (3) Hartzell T10173() and T10176() aluminum blades with no prefix letter or an "A" prefix letter in the blade serial number, except blade serial numbers listed in Table 1, are affected by this Service Bulletin

NOTE: A previous revision of this Service Bulletin required shot peening of the blade retention radius on "Y" shank blades. Shot peening of the blade retention radius is no longer required.

B. Reason

- (1) Hartzell has received reports from the field of corrosion in the blade balance hole.
- (2) This corrosion could precipitate fatigue cracks and result in failures of the blade.

C. Description

- (1) This Service Bulletin provides instructions for inspection of the blade bore, blade balance hole, and inspection of the blade shank.
- (2) This Service Bulletin is issued as an alternate method of compliance for AD 72-08-04.

HARTZELL PROPELLER INC.
SERVICE BULLETIN
HC-SB-61-97A
Propellers - Blade Inspection

A97324	B63294	B80715	B82711
A97352	B63327	B80717	B82876
A98330	B63354	B80895	B82878
B38602	B63431	B80908	B82883
B39183	B63441	B80911	B82891
B39356	B69570	B80988	B82894
B40809	B71482	B82181	B82895
B40828	B71483	B82182	B82898
B41002	B75009	B82215	B82900
B41387	B75037	B82565	B82902
B41886	B75322	B82566	B82905
B41893	B76844	B82577	B82908
B44241	B76847	B82579	B84129
B44343	B76865	B82586	B84168
B49153	B78383	B82595	B84169
B53160	B78386	B82598	B84187
B53246	B78428	B82599	B84192
B53249	B79430	B82603	B84193
B53264	B79435	B82607	B84222
B63036	B79454	B82685	B84227
B63039	B80547	B82694	B84230
B63122	B80548	B82699	B84243
B63127	B80553	B82706	B84245
B63131	B80698	B82710	B84254
			B84294

Serial Numbers of Propellers Not Affected
Table 1

HARTZELL PROPELLER INC.
SERVICE BULLETIN
HC-SB-61-97A
Propellers - Blade Inspection

D. Compliance

- (1) At next propeller overhaul, not to exceed 1500 hours TSN or TSO, inspect the blade shank, the blade bore, and the blade balance hole, and shot peen the blade balance hole in accordance with the Accomplishment Instructions of this Service Bulletin.
- (2) T10173-() Non-Category II propeller blade used on Beech 99 and A99 aircraft:
 - (a) Within 1500 hours time in service after accomplishment of the blade inspection and shot peening of the blade balance hole in accordance with the Accomplishment Instructions of this Service Bulletin, replace the T10173-() Non-Category II blades with T10173-() Category II type blades in accordance with the Accomplishment Instructions of this Service Bulletin.
 - (b) A T10173-() Non-Category II blade from a Beech 99 or an A99 aircraft that is affected by this Service Bulletin is not to be removed and reused on another aircraft application. Such blade interchangeability is no longer authorized.
 - (c) Hartzell propeller overhaul requirements are specified in Hartzell Service Letter HC-SL-61-61Y.

E. Approval

- (1) This Service Bulletin is approved by the Manager, FAA, Chicago Aircraft Certification Office, ACE115C, by approval document dated April 16, 2007 as an alternate method of compliance for AD 72-08-04.

F. References

- (1) Hartzell Steel Hub Turbine Propeller Maintenance Manual 118F (61-10-18)
- (2) Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33)
- (3) Hartzell Propeller Owner's Manual 139 (61-00-39)
- (4) Hartzell Standard Practices Manual 202A (61-00-02).
- (5) Airworthiness Directive 72-08-04

HARTZELL PROPELLER INC.
SERVICE BULLETIN
HC-SB-61-97A
Propellers - Blade Inspection

2. Accomplishment Instructions

- A. Remove the propeller from the aircraft in accordance with the Hartzell Propeller Owner's Manual 139 (61-00-39).
- B. Disassemble the propeller in accordance with the Hartzell Steel Hub Turbine Propeller Maintenance Manual 118F (61-10-18).
- C. For Beech 99 or A99 aircraft, remove and replace T10173() Non-category II blades with Category II blades in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33). Blades must be retired from service in accordance with the Part Retirement Procedures chapter of Hartzell Standard Practices Manual 202A (61-00-02).
- D. Remove components from the blade in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33).
 - (1) Remove the bearing from the blade bore.
 - (2) Remove the lead from the balance hole, if applicable.
 - (3) Remove the paint from the blade bore and the blade balance hole.
- E. Inspect the blade bore, the blade balance hole and the blade shank in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33).
- F. Shot peen the blade balance hole in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33).
- G. Apply chemical conversion coating and paint to the blade bore and the blade balance hole in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33).
- H. Apply chemical conversion coating to the blade shank in accordance with Hartzell Aluminum Blade Overhaul Manual 133C (61-13-33).
- I. Assemble the propeller in accordance with the Hartzell Steel Hub Turbine Propeller Maintenance Manual 118F (61-10-18).
- J. Install the propeller on the aircraft in accordance with the Hartzell Propeller Owner's Manual 139 (61-10-39).