



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ()7690(),7890(),B7421(),E8190()
 - 2: N7605(B,K)(),N()7893(-)()
 - 3: E9193()
 - 4: E13890()
 - 5: A10460(),E10950(),E11990(),E12902()
 - 6: M10083(),LM10585()+4,M10877()
 - 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
 - 8: NC8834(),(J)NC10904(),JNC10905().
 - 9: 108MH92,138MH91
 - 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Argentina			
<i>Helices Clerici Buenos Aires</i>	<i>4/30/19</i>	<i>None Approved</i>	<i>N/A</i>
Australia			
<i>Airbus Group Australia Dingley Victoria</i>	<i>2/28/22</i>	<i>3</i>	<i>2/28/28</i>
<i>Airflite Pty. Ltd. Perth Western Australia</i>	<i>9/30/21</i>	<i>7</i>	<i>8/31/28</i>
<i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i>	<i>#3/28/22</i>	<i>1,7</i>	<i>8/31/27</i>
<i>Prop Care Australia Pty Ltd. Brisbane Queensland</i>	<i>9/30/21</i>	<i>None Approved</i>	<i>N/A</i>
<i>West Coast Propellers Pty. Ltd. Perth Western Australia</i>	<i>2/28/22</i>	<i>3,7,8</i>	<i>5/31/28</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Brazil</i>			
<i>Diamond Aviação Ltda</i> <i>Goias</i>	<i>10/31/19</i>	<i>1,2,7,8</i>	<i>7/31/26</i>
<i>Canada</i>			
AMK Aviation Inc. Murrillo Ontario	6/30/20	5	3/31/28
<i>Canadian Propeller</i> <i>Winnipeg</i> <i>Manitoba</i>	<i>#2/28/21</i>	<i>2,5,6,7</i>	<i>11/30/27</i>
<i>Hope Aero Propeller and Components</i> <i>Mississauga</i> <i>Ontario</i>	<i>1/31/20</i>	<i>2,5,6,7</i>	<i>3/31/26</i>
Propworks Propeller Edmonton Alberta	9/30/21	5	8/31/26
Propworks Propeller Winnipeg	9/30/22	None Approved	N/A
Wasaya Prop Shop LP Thunder Bay Ontario	4/30/20	5	9/30/21



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/20	5,6	7/31/20
China			
Shenyang Avias Shenyang	5/30/20	None Approved	N/A
France			
Technic Aviation Manosque	None	3,5,6,7,8	2/28/27
Germany			
Hoffmann GmbH and Co., KG Rosenheim Bavaria	3/31/23	None Approved	N/A
MT Propeller GmbH Atting	#4/30/20	1,2,4,5,6,7,10	5/31/29



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Röder Präzision GmbH Egelsbach Hessen</i>	<i>2/28/22</i>	<i>None Approved</i>	<i>N/A</i>
<i>Mexico</i>			
<i>ASI Propeller</i>	<i>12/31/22</i>	<i>None Approved</i>	<i>N/A</i>
<i>New Zealand</i>			
<i>Airbus New Zealand Blenheim</i>	<i>None</i>	<i>2,5</i>	<i>7/31/23</i>
<i>Norway</i>			
<i>Norronafly P & P AS Oslo</i>	<i>None</i>	<i>5,6</i>	<i>11/30/22</i>
<i>Portugal</i>			
<i>Aerohelice LDA Alverca</i>	<i>6/30/19</i>	<i>2,5</i>	<i>12/31/26</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Singapore</i>			
<i>C & A Aviation Ltd. Seletar</i>	<i>4/30/19</i>	<i>5,6</i>	<i>10/31/21</i>
<i>South Africa</i>			
Joc-Air Pretoria	9/30/22	1,2,5,6,7	1/31/29
Propeller Centre Les Marais Pretoria	2/28/21	2,5,6,7	1/31/26
<i>Switzerland</i>			
Pilatus Aircraft	9/30/22	3,7	05/31/29
<i>United Kingdom</i>			
<i>Brinkley Propeller Services LTD Nr Shefford Bedfordshire</i>	<i>12/31/22</i>	<i>2,7</i>	<i>N/A</i>
<i>Proptech Portsmouth LTD Portsmouth Hampshire</i>	<i>#6/30/20</i>	<i>2,3,4,5,6</i>	<i>11/30/24</i>

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing

* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location <i>USA</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Aircraft Propeller Service Inc. Wheeling Illinois	None	None Approved	N/A
<i>American Propeller Service Redding California</i>	<i>10/31/21</i>	<i>1,2,5,6,7,8</i>	<i>3/31/28</i>
Aircraft Propeller Works Auburndale Florida	4/30/20	2,7	12/31/26
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>10/31/21</i>	<i>5,6</i>	<i>11/30/25</i>
Great Lakes Aviation Cheyenne Wyoming	6/30/19	5,6	3/31/21
<i>Hartzell Service Center Piqua Ohio</i>	<i>#8/31/20</i>	<i>1,2,3,4,5,6,7,8,9,10</i>	<i>5/31/27</i>
<i>Jordan Propeller Service, Inc. San Antonio Texas</i>	<i>#2/28/22</i>	<i>None Approved</i>	<i>N/A</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>InterContinental Jet Oklahoma</i>	<i>2/28/22</i>	<i>5</i>	<i>3/31/29</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>3/31/23</i>	<i>None Approved</i>	<i>N/A</i>
New England Propeller Service East Haddam Connecticut	#6/30/20	1,2,4,5,6,7,8,10	10/31/27
<i>Northwest Propeller Service, Inc. Puyallup Washington</i>	<i>10/31/19</i>	<i>None Approved</i>	<i>N/A</i>
<i>Ottosen Propeller Phoenix Arizona</i>	<i>#None</i>	<i>None Approved</i>	<i>N/A</i>
<i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i>	<i>9/30/22</i>	<i>2,5</i>	<i>6/30/27</i>
Santa Monica Propeller Santa Monica California	None	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	6/30/20	None Approved	N/A



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Sensenich Propeller Service, Inc. Lititz Pennsylvania	6/30/20	2,5,6,7,10	None
Sullivan Propeller Hayward California	6/30/19	None Approved	N/A
Texas Aircraft Propeller Pearland Texas	12/31/22	None Approved	N/A
Tiffin Aire Tiffin Ohio	#5/30/20	1,2,5,6,7,8,10	10/31/26
Yingling Aircraft Inc. Wichita Kansas	12/31/22	None Approved	N/A
Venezuela			
Aero Helices De Venezuela Edo. Miranda	5/30/20	None Approved	N/A
Tecniprop CA	None	None Approved	N/A