## UNAPPROVED PARTS NOTIFICATION

# SUSPECTED UNAPPROVED PARTS PROGRAM OFFICE, AVR-20 45005 AVIATION DRIVE, SUITE 214 DULLES, VA 20166-7541

U.S. Department of Transportation Federal Aviation Administration

UPNs are posted on the internet at http://www.faa.gov/avr/sups.htm

No. 99-147 July 17, 2000

Published by: FAA, AFS-610, P.O. Box 26460, Oklahoma City, OK 73125

#### AFFECTED PARTS

Hartzell Aluminum Propeller Blades – Compact Series.

#### PURPOSE

This notice is to advise all aircraft owners, operators, maintenance entities, and parts suppliers and distributors

that certain Hartzell aluminum propeller blades overhauled by Precision Propeller, Inc. (Air Agency

Certificate #AZER344C), Tuscaloosa, Alabama, may not have been overhauled in accordance with the

manufacturer's overhaul manual. Evidence also exists that during maintenance or overhaul of Hartzell

propellers, Precision Propeller, Inc., did not accomplish all requirements of Airworthiness Directive

(AD) 77-12-06 and Hartzell Service Bulletin 118D.

#### BACKGROUND

Incident to a Federal Aviation Administration (FAA) suspected unapproved parts investigation, it was

determined that Precision Propeller, Inc., was not qualified to perform the cold compression roll process

required by AD 77-12-06, Hartzell Service Bulletin 118D, and the Hartzell Aluminum Blade Overhaul

Manual – 133C. Evidence exists that Precision Propeller, Inc., performed the cold compression rolling

process from January 1994 through April 1999.

### RECOMMENDATION

Regulations require that type-certificated products conform to their type design. It is recommended that

aircraft, aircraft records, and aircraft parts inventories be inspected and reviewed for propellers that have been

repaired, inspected, and/or overhauled by Precision Propeller, Inc., of Tuscaloosa, Alabama. If any of these

parts are installed or found in existing stock, it is recommended that appropriate action should be taken to

ensure all requirements of Airworthiness Directive (AD) 77-12-06, Hartzell Service Bulletin 118D, and

Hartzell Aluminum Blade Overhaul Manual have been accomplished.

#### **FURTHER INFORMATION**

Further information regarding this notice may be obtained from the FAA Flight Standards District Office

(FSDO) indicated below. The FAA would appreciate any information concerning the condition, status, and

the discovery of the above-referenced parts from any source, the means to identify the source, and the actions

taken to remove the parts from aircraft and/or stock. This notice originated from the Alabama FSDO,

1500 Urban Center Dr., Vestavia Hills, AL 35242, telephone (205) 731-1557, ext. 132, fax (205) 731-0939;

and was published through the FAA Suspected Unapproved Parts Program Office, AVR-20,

telephone (703) 661-0581, fax (703) 661-0113.