



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ()7690(),7890(),B7421(),E8190()
 - 2: N7605(B,K)(),N()7893(-)()
 - 3: E9193()
 - 4: E13890()
 - 5: A10460(),E10950(),E11990(),E12902()
 - 6: M10083(),LM10585()+4,M10877()
 - 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
 - 8: NC8834(),(J)NC10904(),JNC10905().
 - 9: 108MH92,138MH91
 - 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Argentina			
<i>Helices Clerici Buenos Aires</i>	<i>Not Approved</i>	<i>None Approved</i>	<i>N/A</i>
Australia			
<i>Airbus Group Australia Dingley Victoria</i>	<i>2/28/22</i>	<i>3</i>	<i>2/28/28</i>
<i>Airflite Pty. Ltd. Perth Western Australia</i>	<i>9/30/21</i>	<i>6,7</i>	<i>4/30/30</i>
<i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i>	<i>#3/28/22</i>	<i>1,7</i>	<i>8/31/27</i>
<i>Prop Care Australia Pty Ltd. Brisbane Queensland</i>	<i>9/30/21</i>	<i>None Approved</i>	<i>N/A</i>
<i>West Coast Propellers Pty. Ltd. Perth Western Australia</i>	<i>2/28/22</i>	<i>3,7,8</i>	<i>5/31/28</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Brazil			
<i>Diamond Aviação Ltda</i> <i>Goias</i>	<i>3/31/24</i>	<i>1,2,7,8</i>	<i>7/31/26</i>
Canada			
AMK Aviation Inc. Murrillo Ontario	3/31/24	5	3/31/28
<i>Canadian Propeller</i> <i>Winnipeg Manitoba</i>	<i>#2/28/21</i>	<i>2,5,6,7</i>	<i>11/30/27</i>
<i>Hope Aero Propeller and Components</i> <i>Mississauga Ontario</i>	<i>Not Approved</i>	<i>2,5,6,7,10</i>	<i>9/30/29</i>
Propworks Propeller Edmonton Alberta	3/31/24	5,7	9/30/29
Propworks Propeller Winnipeg	9/30/22	None Approved	N/A
Wasaya Prop Shop LP Thunder Bay Ontario	Not Approved	5	**9/30/21



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/21	5,6	7/31/30
China			
Shenyang Avias Shenyang	Not Approved	None Approved	N/A
Columbia			
General Propeller Services SAS Bogata	9/30/23	None Approved	N/A
France			
Technic Aviation Manosque	Not Approved	**(3,5,6,7,8)	**2/28/27
Germany			
Hoffmann GmbH and Co., KG Rosenheim Bavaria	3/31/23	None Approved	N/A



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
MT Propeller GmbH Atting	#3/31/24	1,2,4,5,6,7,10	5/31/29
<i>Röder Präzision GmbH Egelsbach Hessen</i>	<i>2/28/22</i>	<i>None Approved</i>	<i>N/A</i>
<i>Malaysia</i>			
<i>C & A Aviation Ltd.</i>	<i>Not Approved</i>	<i>**5,6</i>	<i>**10/31/21</i>
<i>Mexico</i>			
ASI Propeller	12/31/22	None Approved	N/A
<i>New Zealand</i>			
<i>Airbus New Zealand Blenheim</i>	<i>Not Approved</i>	<i>** (2,5)</i>	<i>**7/31/23</i>
<i>Norway</i>			
<i>Norronafly P & P AS Oslo</i>	<i>Not Approved</i>	<i>** (5,6)</i>	<i>**11/30/22</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ()7690(),7890(),B7421(),E8190()
 - 2: N7605(B,K)(),N()7893(-)()
 - 3: E9193()
 - 4: E13890()
 - 5: A10460(),E10950(),E11990(),E12902()
 - 6: M10083(),LM10585()+4,M10877()
 - 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
 - 8: NC8834(),(J)NC10904(),JNC10905().
 - 9: 108MH92,138MH91
 - 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Portugal</i>			
Aerohelice LDA Alverca	Not Approved	**2,5	**12/31/26
<i>South Africa</i>			
Joc-Air Pretoria	9/30/22	1,2,5,6,7	1/31/29
Propeller Centre Les Marais Pretoria	2/28/21	2,5,6,7	1/31/26
<i>Switzerland</i>			
Pilatus Aircraft	9/30/22	3,7	05/31/29
<i>United Kingdom</i>			
<i>Brinkley Propeller Services LTD</i> <i>Nr Shefford Bedfordshire</i>	<i>12/31/22</i>	<i>2,7,8,10</i>	<i>5/31/30</i>
<i>Proptech Portsmouth LTD</i> <i>Portsmouth Hampshire</i>	<i>#6/30/21</i>	<i>2,3,4,5,6</i>	<i>11/30/24</i>

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing

* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),76CO3().

Company/Location <i>USA</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Aircraft Propeller Service Inc. Wheeling Illinois	Not Approved	None Approved	N/A
<i>American Propeller Service Redding California</i>	<i>10/31/21</i>	<i>1,2,5,6,7,8,10</i>	<i>9/30/28</i>
Aircraft Propeller Works Auburndale Florida	3/31/24	2,6,7,10	9/30/29
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>10/31/21</i>	<i>5,6</i>	<i>11/30/25</i>
Great Lakes Aviation Cheyenne Wyoming	Not Approved	**5,6	**3/31/21
<i>Hartzell Service Center Piqua Ohio</i>	<i>#8/31/20</i>	<i>1,2,3,4,5,6,7,8,9,10</i>	<i>5/31/27</i>
<i>Jordan Propeller Service, Inc. San Antonio Texas</i>	<i>#2/28/22</i>	<i>2,7</i>	<i>11/30/2029</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>InterContinental Jet Oklahoma</i>	<i>2/28/22</i>	<i>1,2,5,6</i>	<i>6/30/30</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>2/28/23</i>	<i>1,2,7,10</i>	<i>6/30/30</i>
New England Propeller Service East Haddam Connecticut	#6/30/21	1,2,4,5,6,7,8,10	10/31/27
<i>Northwest Propeller Service, Inc. Puyallup Washington</i>	<i>2/28/23</i>	<i>None Approved</i>	<i>N/A</i>
<i>Ottosen Propeller Phoenix Arizona</i>	<i>#Not Approved</i>	<i>None Approved</i>	<i>N/A</i>
<i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i>	<i>9/30/22</i>	<i>2,5</i>	<i>6/30/27</i>
Santa Monica Propeller Santa Monica California	Not Approved	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	Not Approved	None Approved	N/A



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),N()8302()-(),
N76MO5C()X,NC10320(), NC10245().
- 8: NC8834(),(J)NC10904(),JNC10905().
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(),
76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Sensenich Propeller Service, Inc. Lititz Pennsylvania	Not Approved	None Approved	None
Sullivan Propeller Hayward California	Not Approved	None Approved	N/A
<i>Texas Aircraft Propeller</i> Pearland Texas	12/31/22	None Approved	N/A
Tiffin Aire Tiffin Ohio	#8/31/21	1,2,5,6,7,8,10	10/31/26
Yingling Aircraft Inc. Wichita Kansas	12/31/22	None Approved	N/A
<i>Venezuela</i>			
Aero Helices De Venezuela Edo. Miranda	Not Approved	None Approved	N/A