Hartzell Propeller, Inc
One Propeller Place
Piqua OH 45356-2634

HP3235IM

INSTRUCTIONS FOR INSTALLATION OF A

HARTZELL HC-C3YR-1RF/F7693F PROPELLER

AND C-3535-1(P) SPINNER

ON PIPER PA-28-235 AIRCRAFT

Rev No.	Page No.	Date	Discription
Origional	Title 1-1	July 30, 2001	Complete manual

FAA Approved R. Perrin Date Aug. 13, 2001

Hartzell Propeller, Inc
One Propeller Place
Piqua, OH 45356-2634

AFM supplement to
Piper PA28-235 AFM
STC SA 01190LA

Supplement No HP3235F

LOG OF PAGES

Rev No.	Page No.	Date	Description	FAA APPROVED
Original	Title Log 1	23 July 2001 23 July 2001 23 July 2001	Complete Supplement	Mgr. Flt Test Br. ANM-160L FAA. LosAngeles ACO Transport Airplane Directorate Date 23 July 2001

Revised pages marked with " * " symbol

Hartzell Propeller, Inc
One Propeller Place
Piqua OH 45356-2634

HP3235IM

INSTRUCTIONS FOR INSTALLATION OF A HARTZELL HC-C3YR-1RF/F7693F PROPELLER AND C-3535-1(P) SPINNER ON PIPER PA-28-235 AIRCRAFT

1. Remove original propeller and spinner.

2. Install new propeller and spinner in accordance with Hartzell Owner's Manual number 115(N) or latest revision.

3. Attach Hartzell Propeller Inc. Airplane Flight Manual Supplement to existing Piper Airplane Flight Manual.

4. Revise weight and balance records to show the removal of the original propeller and spinner (using data provided in the Airplane Flight Manual Equipment List) and the addition of the following equipment at the same moment arm:

	Weight
Propeller, Hartzell (Pounds) (HC-C3YR-1RF/F7693F)	73
+	
Spinner, Hartzell (C-3535-1(P))	4.5

5. Return aircraft to service with FAA Form 337 referencing STC.

FAA Approved R. Prewitt Date Aug. 13, 2001