



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ()7690(),7890(),B7421(),E8190()
 - 2: N7605(B,K)(),N()7893(-)()
 - 3: E9193()
 - 4: E13890()
 - 5: A10460(),E10950(),E11990(),E12902()
 - 6: M10083(),LM10585()+4,M10877()
 - 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
 - 8: NC8834
 - 9: 108MH92,138MH91
 - 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3()

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Argentina</i>			
<i>Helices Clerici Buenos Aires</i>	<i>4/30/19</i>	<i>None Approved</i>	<i>N/A</i>
<i>Australia</i>			
<i>Airflite Pty. Ltd. Perth Western Australia</i>	<i>6/30/20</i>	<i>None Approved</i>	<i>N/A</i>
<i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i>	<i>6/30/18#</i>	<i>None Approved</i>	<i>N/A</i>
<i>Prop Care Australia Pty Ltd. Brisbane Queensland</i>	<i>8/31/17</i>	<i>None Approved</i>	<i>N/A</i>
<i>West Coast Propellers Pty. Ltd. Perth Western Australia</i>	<i>6/30/20</i>	<i>None Approved</i>	<i>N/A</i>
<i>Brazil</i>			
<i>Diamond Aviação Ltda Goias</i>	<i>10/31/19</i>	<i>1,7,8</i>	<i>7/31/26</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
- 8: NC8834
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3()

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Canada			
<i>Canadian Propeller Winnipeg Manitoba</i>	<i>6/30/19</i>	<i>5,6</i>	<i>9/30/21</i>
<i>Hope Aero Propeller and Components Mississauga Ontario</i>	<i>1/31/20</i>	<i>2,5,6,7</i>	<i>3/31/26</i>
Propworks Propeller Edmonton Alberta	6/30/19	5	8/31/2026
Wasaya Prop Shop LP Thunder Bay Ontario	4/30/20	5	9/30/21
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/20	5,6	7/31/20
China			
Shenyang Avias Shenyang	6/30/20	None Approved	N/A



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
- 8: NC8834
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3()

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
France			
<i>Technic Aviation Manosque</i>	<i>10/31/17</i>	<i>3,5,6,7,8</i>	<i>2/28/27</i>
Germany			
<i>Hoffmann GmbH and Co., KG Rosenheim Bavaria</i>	<i>None</i>	<i>None Approved</i>	<i>N/A</i>
<i>MT Propeller GmbH Atting</i>	<i>4/30/17#</i>	<i>1,2,4,5,6,7</i>	<i>12/31/24</i>
<i>Röder Präzision GmbH Egelsbach Hessen</i>	<i>5/31/18</i>	<i>None Approved</i>	<i>N/A</i>
New Zealand			
<i>Safe Air Ltd Blenheim</i>	<i>5/31/18</i>	<i>2,5</i>	<i>7/31/23</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
 8: NC8834
 9: 108MH92,138MH91
 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Norway			
<i>Norrnafly P & P AS 1330 Fornebu</i>	<i>None</i>	<i>5,6</i>	<i>**11/30/22</i>
Portugal			
<i>Aerohelice LDA Alverca</i>	<i>6/30/19</i>	<i>2,5</i>	<i>12/31/26</i>
Singapore			
<i>C & A Aviation Ltd. Seletar</i>	<i>4/30/19</i>	<i>5,6</i>	<i>10/31/21</i>
South Africa			
<i>Joc-Air Pretoria</i>	<i>6/30/18</i>	<i>2,5,6,7</i>	<i>12/31/26</i>
<i>Propeller Centre Les Marais Pretoria</i>	<i>8/31/17</i>	<i>2,5,6,7</i>	<i>1/31/26</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
 8: NC8834
 9: 108MH92,138MH91
 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3().

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
United Kingdom			
Brinkley Propeller Services LTD Nr Shefford Bedfordshire	6/30/18	None Approved	N/A
Proptech Portsmouth LTD Portsmouth Hampshire	6/30/20[#]	2,3,4,5,6	11/30/24
USA			
Aircraft Propeller Service Inc. Wheeling Illinois	5/31/18	None Approved	N/A
American Propeller Service Redding California	5/31/18	1,2,5,6	10/31/21
Aircraft Propeller Works Auburndale Florida	4/30/20	2,7	12/31/2026
Aviation Propellers Inc. Opa Locka Florida	9/30/17	5,6	11/30/2025
Great Lakes Aviation Cheyenne Wyoming	6/30/19	5,6	3/31/21



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
- 8: NC8834
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3()

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Hartzell Service Center Piqua Ohio</i>	<i>8/31/20[#]</i>	<i>1,2,3,4,5,6,7,8,9,10</i>	<i>5/31/27</i>
<i>Jordan Propeller Service, Inc. San Antonio Texas</i>	<i>5/31/17[#]</i>	<i>5,6</i>	<i>8/31/18</i>
InterContinental Jet Oklahoma	8/31/17	None Approved	N/A
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>8/31/17</i>	<i>None Approved</i>	<i>N/A</i>
New England Propeller Service East Haddam Connecticut	6/30/20 [#]	1,2,4,5,6,7,8	4/30/25
<i>Northwest Propeller Service, Inc. Puyallup Washington</i>	<i>10/31/19</i>	<i>None Approved</i>	<i>N/A</i>
<i>Ottosen Propeller Phoenix Arizona</i>	<i>None[#]</i>	<i>None Approved</i>	<i>N/A</i>
<i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i>	<i>4/30/20</i>	<i>2,5</i>	<i>6/30/2027</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(), N76MO5C()X, NC10245()
- 8: NC8834
- 9: 108MH92,138MH91
- 10: ()75AO1-2(),L76AO1X(),78D01(),H79AO6X(), 76CO3()

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Santa Monica Propeller Santa Monica California	6/30/18	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	6/30/20	None Approved	N/A
Sensenich Propeller Service, Inc. Lititz Pennsylvania	6/30/20	2,5,6	7/31/20
Sullivan Propeller Hayward California	6/30/19	None Approved	N/A
Tiffin Aire Tiffin Ohio	6/30/20 [#]	1,2,5,6,7,8,10	9/30/18
Yingling Aircraft Inc. Wichita Kansas	6/30/19	None Approved	N/A
Venezuela			
Aero Helices De Venezuela Edo. Miranda	6/30/20	None Approved	N/A
Tecniprop CA	6/30/18	None Approved	N/A

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing
 * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319