



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b>Argentina</b>			
<b><i>Helices Clerici Buenos Aires</i></b>	<b><i>4/30/19</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b>Australia</b>			
<b><i>Airbus Group Australia Dingley Victoria</i></b>	<b><i>2/28/22</i></b>	<b><i>3</i></b>	<b><i>2/28/2028</i></b>
<b><i>Airflite Pty. Ltd. Perth Western Australia</i></b>	<b><i>9/30/21</i></b>	<b><i>7</i></b>	<b><i>8/31/28</i></b>
<b><i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i></b>	<b><i>#None</i></b>	<b><i>7</i></b>	<b><i>8/31/27</i></b>
<b><i>Prop Care Australia Pty Ltd. Brisbane Queensland</i></b>	<b><i>9/30/21</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>West Coast Propellers Pty. Ltd. Perth Western Australia</i></b>	<b><i>2/28/22</i></b>	<b><i>3,7,8</i></b>	<b><i>5/31/28</i></b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( )
- 8: NC8834( ),(J)NC10904( ),JNC10905( )
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( )

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b>Brazil</b>			
<b><i>Diamond Aviação Ltda</i></b> <b><i>Goias</i></b>	<b><i>10/31/19</i></b>	<b><i>1,2,7,8</i></b>	<b><i>7/31/26</i></b>
<b>Canada</b>			
AMK Aviation Inc. Murrillo Ontario	6/30/20	5	3/31/28
<b><i>Canadian Propeller</i></b> <b><i>Winnipeg Manitoba</i></b>	<b><i>#2/28/21</i></b>	<b><i>2,5,6,7</i></b>	<b><i>11/30/27</i></b>
<b><i>Hope Aero Propeller and Components</i></b> <b><i>Mississauga Ontario</i></b>	<b><i>1/31/20</i></b>	<b><i>2,5,6,7</i></b>	<b><i>3/31/26</i></b>
Propworks Propeller Edmonton Alberta	9/31/21	5	8/31/26
Wasaya Prop Shop LP Thunder Bay Ontario	4/30/20	5	9/30/21
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/20	5,6	7/31/20



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b>China</b>			
Shenyang Avias Shenyang	5/30/20	None Approved	N/A
<b>France</b>			
<b>Technic Aviation Manosque</b>	<b>None</b>	<b>3,5,6,7,8</b>	<b>2/28/27</b>
<b>Germany</b>			
<b>Hoffmann GmbH and Co., KG Rosenheim Bavaria</b>	<b>2/28/22</b>	<b>None Approved</b>	<b>N/A</b>
MT Propeller GmbH Atting	#4/30/20	1,2,4,5,6,7	12/31/24
<b>Röder Präzision GmbH Egelsbach Hessen</b>	<b>2/28/22</b>	<b>None Approved</b>	<b>N/A</b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b><i>New Zealand</i></b>			
<b><i>Airbus New Zealand Blenheim</i></b>	<b><i>None</i></b>	<b><i>2,5</i></b>	<b><i>7/31/23</i></b>
<b><i>Norway</i></b>			
<b><i>Norronafly P &amp; P AS Oslo</i></b>	<b><i>None</i></b>	<b><i>5,6</i></b>	<b><i>11/30/22</i></b>
<b><i>Portugal</i></b>			
<b><i>Aerohelice LDA Alverca</i></b>	<b><i>6/30/19</i></b>	<b><i>2,5</i></b>	<b><i>12/31/26</i></b>
<b><i>Singapore</i></b>			
<b><i>C &amp; A Aviation Ltd. Seletar</i></b>	<b><i>4/30/19</i></b>	<b><i>5,6</i></b>	<b><i>10/31/21</i></b>
<b><i>South Africa</i></b>			
<b><i>Joc-Air Pretoria</i></b>	<b><i>9/30/22</i></b>	<b><i>2,5,6,7</i></b>	<b><i>12/31/26</i></b>

**Composite Blade Overhaul and Erosion Shield Replacement Approval Listing**  
 \* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319v



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( )
- 8: NC8834( ),(J)NC10904( ),JNC10905( )
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( )

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Propeller Centre Les Marais Pretoria	2/28/21	2,5,6,7	1/31/26
<b>United Kingdom</b>			
<b><i>Brinkley Propeller Services LTD Nr Shefford Bedfordshire</i></b>	<b><i>None</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>Proptech Portsmouth LTD Portsmouth Hampshire</i></b>	<b><i>#6/30/20</i></b>	<b><i>2,3,4,5,6</i></b>	<b><i>11/30/24</i></b>
<b>USA</b>			
Aircraft Propeller Service Inc. Wheeling Illinois	None	None Approved	N/A
<b><i>American Propeller Service Redding California</i></b>	<b><i>10/31/21</i></b>	<b><i>1,2,5,6,7,8</i></b>	<b><i>3/31/28</i></b>
Aircraft Propeller Works Auburndale Florida	4/30/20	2,7	12/31/26
<b><i>Aviation Propellers Inc. Opa Locka Florida</i></b>	<b><i>10/31/21</i></b>	<b><i>5,6</i></b>	<b><i>11/30/25</i></b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( )
- 8: NC8834( ),(J)NC10904( ),JNC10905( )
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( )

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Great Lakes Aviation Cheyenne Wyoming	6/30/19	5,6	3/31/21
<b>Hartzell Service Center</b> <b>Piqua Ohio</b>	<b>#8/31/20</b>	<b>1,2,3,4,5,6,7,8,9,10</b>	<b>5/31/27</b>
<b>Jordan Propeller Service, Inc.</b> <b>San Antonio Texas</b>	<b>#2/28/22</b>	<b>5,6</b>	<b>N/A</b>
InterContinental Jet Oklahoma	2/28/22	None Approved	N/A
<b>Maxwell Aircraft Service</b> <b>Minneapolis Minnesota</b>	<b>None</b>	<b>None Approved</b>	<b>N/A</b>
New England Propeller Service East Haddam Connecticut	#6/30/20	1,2,4,5,6,7,8,10	10/31/27
<b>Northwest Propeller Service, Inc.</b> <b>Puyallup Washington</b>	<b>10/31/19</b>	<b>None Approved</b>	<b>N/A</b>
<b>Ottosen Propeller</b> <b>Phoenix Arizona</b>	<b>#None</b>	<b>None Approved</b>	<b>N/A</b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b><i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i></b>	<b><i>9/30/22</i></b>	<b><i>2,5</i></b>	<b><i>6/30/27</i></b>
Santa Monica Propeller Santa Monica California	None	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	6/30/20	None Approved	N/A
Sensenich Propeller Service, Inc. Lititz Pennsylvania	6/30/20	2,5,6,7,10	None
Sullivan Propeller Hayward California	6/30/19	None Approved	N/A
Tiffin Aire Tiffin Ohio	#5/30/20	1,2,5,6,7,8,10	10/31/26
Yingling Aircraft Inc. Wichita Kansas	6/30/19	None Approved	N/A



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**  
 1: ( )7690( ),7890( ),B7421( ),E8190( )  
 2: N7605(B,K)( ),N( )7893(-)( )  
 3: E9193( )  
 4: E13890( )  
 5: A10460( ),E10950( ),E11990( ),E12902( )  
 6: M10083( ),LM10585( )+4,M10877( )  
 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),  
 N76MO5C( )X,NC10320( ), NC10245( ).  
 8: NC8834( ),(J)NC10904( ),JNC10905( ).  
 9: 108MH92,138MH91  
 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),  
 76CO3( ).

<b>Company/Location</b>	<b>Overhaul/Major Repair Expiration</b>	<b>Erosion Shield Replacement Approved Blade Families</b>	<b>Erosion Shield Replacement Approval Expiration</b>
<b><i>Venezuela</i></b>			
<b><i>Aero Helices De Venezuela Edo. Miranda</i></b>	<b><i>5/30/20</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>Tecniprop CA</i></b>	<b><i>None</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>