



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

- Blade Families**
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Argentina			
<i>Helices Clerici Buenos Aires</i>	<i>4/30/19</i>	<i>None Approved</i>	<i>N/A</i>
Australia			
<i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i>	<i>6/30/18#</i>	<i>None Approved</i>	<i>N/A</i>
<i>Prop Care Australia Pty Ltd. Brisbane Queensland</i>	<i>8/31/17</i>	<i>None Approved</i>	<i>N/A</i>
<i>West Coast Propellers Pty. Ltd. Success Western Australia</i>	<i>11/30/17</i>	<i>None Approved</i>	<i>N/A</i>
Brazil			
<i>Diamond Aviação Ltda Goias</i>	<i>10/31/19</i>	<i>N7605()</i>	<i>11/30/24</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
L76AO1X(),N76MO5C()X,H79AO6X()
- 8: NC8834
- 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Canada			
Canadian Propeller Winnipeg Manitoba	6/30/19	5, 6	9/30/21
Hope Aero Propeller and Components Mississauga Ontario	None	5, 6	Not Approved
Propworks Propeller Edmonton Alberta	6/30/19	None Approved	N/A
Propworks Propeller Systems Winnipeg Manitoba	None	None Approved	N/A
Wasaya Prop Shop LP Thunder Bay Ontario	None	5	9/30/21
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/16	5, 6	7/31/20
France			
Technic Aviation Manosque	10/31/17	5,6	12/31/20



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

- Blade Families**
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Germany</i>			
<i>Hoffmann GmbH and Co., KG Rosenheim Bavaria</i>	<i>5/31/17</i>	<i>None Approved</i>	<i>N/A</i>
<i>MT Propeller GmbH Atting</i>	<i>2/28/16[#]</i>	<i>1,2,4,5,6,7</i>	<i>12/31/24</i>
<i>Röder Präzision GmbH Egelsbach Hessen</i>	<i>5/31/18</i>	<i>None Approved</i>	<i>N/A</i>
<i>New Zealand</i>			
<i>Safe Air Ltd Blenheim</i>	<i>5/31/18</i>	<i>2,5</i>	<i>7/31/23</i>
<i>Norway</i>			
<i>Norronafly P & P AS 1330 Fornebu</i>	<i>6/30/16</i>	<i>5,6</i>	<i>11/30/22</i>



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Blade Families
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Portugal</i>			
Aerohelice LDA Alverca	6/30/19	5	12/31/20
<i>Singapore</i>			
<i>C & A Aviation Ltd.</i> <i>Seletar</i>	<i>4/30/19</i>	<i>5, 6</i>	<i>10/31/21</i>
ST Aerospace Systems Pte Ltd Paya Lebar	None	5, 6	Not Approved
<i>South Africa</i>			
Joc-Air Pretoria	6/30/18	2, 5, 6	9/30/24
Propeller Centre Les Marais Pretoria	8/31/17	2,5,7	9/30/25



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Blade Families
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Switzerland			
Ruag Aviation Lodrino	None	None Approved	N/A
United Kingdom			
Brinkley Propeller Services LTD Nr Shefford Bedfordshire	6/30/18	None Approved	N/A
<i>Proptech Portsmouth LTD Portsmouth Hampshire</i>	<i>6/30/19[#]</i>	<i>2, 3, 4, 5, 6</i>	<i>11/30/24</i>
USA			
AAR Oklahoma Oklahoma City Oklahoma	2/28/16 [#]	1, 2, 5, 6	11/30/19
Aircraft Propeller Service Inc. Wheeling Illinois	5/31/18	None Approved	N/A
American Propeller Service Redding California	5/31/18	1, 2, 5, 6	10/31/21



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Blade Families

- 1: ()7690(),7890(),B7421(),E8190()
- 2: N7605(B,K)(),N()7893(-)()
- 3: E9193()
- 4: E13890()
- 5: A10460(),E10950(),E11990(),E12902()
- 6: M10083(),LM10585()+4,M10877()
- 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
L76AO1X(),N76MO5C()X,H79AO6X()
- 8: NC8834
- 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Aircraft Propeller Works Auburndale Florida	*5/31/18	None Approved	N/A
Air Prop Specialists Marianna Florida	None	None Approved	N/A
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>5/31/17</i>	<i>5,6</i>	<i>11/30/2025</i>
Byam Propeller Service Ft. Worth Texas	None	None Approved	N/A
Great Lakes Aviation Cheyenne Wyoming	6/30/19	5, 6	3/31/21
<i>Hartzell Service Center Piqua Ohio</i>	<i>8/31/16[#]</i>	<i>1, 2, 3, 4, 5, 6, 7</i>	<i>7/31/17</i>
<i>Jordan Propeller Service, Inc. San Antonio Texas</i>	<i>5/31/17[#]</i>	<i>5, 6</i>	<i>8/31/18</i>
InterContinental Jet Oklahoma	8/31/17	None Approved	N/A



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Blade Families
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>8/31/17</i>	<i>None Approved</i>	<i>N/A</i>
New England Propeller Service East Haddam Connecticut	6/30/16 [#]	1, 2, 4, 5, 6, 7, 8	4/30/25
<i>Northwest Propeller Service, Inc. Puyallup Washington</i>	<i>10/31/19</i>	<i>None Approved</i>	<i>N/A</i>
<i>Ottosen Propeller Phoenix Arizona</i>	<i>11/30/15[#]</i>	<i>None Approved</i>	<i>N/A</i>
<i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i>	<i>5/31/17</i>	<i>5, 6</i>	<i>N/A</i>
Santa Monica Propeller Santa Monica California	6/30/18	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	6/30/16	None Approved	N/A
Sensenich Propeller Service, Inc. Lititz Pennsylvania	6/30/16	2, 5, 6	7/31/20

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing
 * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Blade Families
 1: ()7690(),7890(),B7421(),E8190()
 2: N7605(B,K)(),N()7893(-)()
 3: E9193()
 4: E13890()
 5: A10460(),E10950(),E11990(),E12902()
 6: M10083(),LM10585()+4,M10877()
 7: NC9208,N7605C(B,K)(),N()8301(),()75AO1-2,
 L76AO1X(),N76MO5C()X,H79AO6X()
 8: NC8834
 9: 108MH92,138MH91

Company/Location		Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Sullivan Propeller Hayward	California	6/30/19	None Approved	N/A
Tiffin Aire Tiffin	Ohio	4/30/16 [#]	1, 2, 5, 6	9/30/18
Warner Propeller Tuscon	Arizona	None	None Approved	N/A
Yingling Aircraft Inc. Wichita	Kansas	6/30/19	None Approved	N/A
<i>Venezuela</i>				
Aero Helices De Venezuela Edo. Miranda		6/30/16	None Approved	N/A
Tecniprop CA		6/30/18	None Approved	N/A