



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Argentina					
A.O.G. SA Cordoba	Not Approved	Not Approved	Not Approved	6/30/2018	Not Approved
Argenprop S.R.L. Pcia de Buenos Aires	9/30/18	9/30/18	6/30/20	6/30/20	9/30/18
Argentine Air Force Amarilo	Not Approved	*12/31/20	Not Approved	12/31/20	12/31/20
Australia					
<i>East Coast Propellers Pty. Ltd.</i> <i>Sydney New South Wales</i>	<i>7/31/18</i>	<i>Not Approved</i>	<i>8/31/19</i>	<i>Not Approved</i>	<i>Not Approved</i>
Prop Care Australia Pty Ltd. Brisbane Queensland	12/31/20	5/31/18	5/31/18	Not Approved	Not Approved
Brazil					
<i>Diamond Aviação Ltda</i> <i>Goias</i>	Not Approved	<i>*3/31/20</i>	<i>2/28/18</i>	<i>3/31/20</i>	Not Approved
Quick Aviacao Ltda Goias	Not Approved	Not Approved	2/28/2020	2/28/2020	Not Approved
Canada					
<i>Canadian Propeller</i> <i>Winnipeg Manitoba</i>	<i>8/31/20</i>	<i>Not Approved</i>	<i>8/31/2020</i>	<i>Not Approved</i>	<i>Not Approved</i>

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<i>Hope Aero Propeller and Components Inc. Mississauga Ontario</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>2/31/20</i>	<i>11/30/18</i>	<i>Not Approved</i>
Propworks Propeller Systems Inc. Edmonton Alberta	6/30/18	*2/28/18	11/30/19	Not Approved	Not Approved
Western Propeller Co. Ltd. Richmond British Columbia	Not Approved	Not Approved	8/31/20	10/31/18	Not Approved
Chile					
Enaer-Empresa Nacional De Aeronautica	Not Approved	Not Approved	Not Approved	7/31/19	Not Approved
China					
Metal Improvement Suzhou Jiangsu	Not Approved	9/30/18	Not Approved	11/30/18	Not Approved
Civil Aviation Flight University of China	Not Approved	Not Approved	Not Approved	1/31/20	Not Approved
France					
<i>Technic Aviation Manosque</i>	<i>4/30/20</i>	<i>*4/30/20</i>	<i>Not Approved</i>	<i>5/31/18</i>	<i>Not Approved</i>
Germany					
<i>Hoffmann GmbH and Co., KG Rosenheim Bavaria</i>	<i>4/30/18</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>

Shot Peening Approval Listing

* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Metal Improvements Co. Feuchtwangen North Rhine	Not Approved	Not Approved	2/28/20	2/28/20	Not Approved
MT Propeller GmbH Atting	10/31/19	10/31/19	8/31/20	10/31/19	10/31/19
India					
Arrow Aviation Services Pty Ltd	Not Approved	Not Approved	8/31/20	Not Approved	Not Approved
Italy					
Pubbli Aer Foto Aero Servizi	3/31/19	Not Approved	Not Approved	3/31/19	Not Approved
Japan					
Jamco Corporation	Not Approved	Not Approved	Not Approved	11/30/20	Not Approved
Nicchu Co, LTD	Not Approved	Not Approved	5/31/19	Not Approved	Not Approved
Malaysia					
<i>C & A Aviation Ltd.</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>4/30/20</i>	<i>Not Approved</i>	<i>Not Approved</i>
Mexico					
Metal Improvement Company LLC	Not Approved	Not Approved	9/30/2019	Not Approved	Not Approved
New Zealand					
<i>Safe Air Ltd Blenheim</i>	<i>4/30/18</i>	<i>4/30/18</i>	<i>4/30/18</i>	<i>4/30/18</i>	<i>Not Approved</i>

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Norway					
<i>Norronafly P & P AS Oslo</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>4/30/18</i>	<i>Not Approved</i>
Portugal					
Aerohelice LDA Alverca	3/31/19	3/31/19	9/30/18	3/31/19	9/30/18
Singapore					
ST Aerospace Systems Pte Ltd Peya Lebar	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
South Africa					
Joc-Air Pretoria	Not Approved	Not Approved	10/31/19	Not Approved	Not Approved
Visser Import and Export Dynamic Propellers Germiston	Not Approved	Not Approved	8/31/20	Not Approved	Not Approved
Switzerland					
Metal Improvement	Not Approved	Not Approved	4/30/20	Not Approved	Not Approved
RUAG Aviation Lodrino	Not Approved	Not Approved	Not Approved	3/31/19	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
United Kingdom					
<i>Brinkley Propeller Services LTD Bedfordshire</i>	<i>10/31/20</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Proptech Portsmouth LTD Portsmouth Hampshire</i>	<i>11/30/18</i>	<i>5/31/19</i>	<i>3/31/18</i>	<i>7/31/18</i>	<i>Not Approved</i>
Uruguay					
Charles Chalkling S.A. Paysandu-C.P.	Not Approved	Not Approved	6/30/20	8/31/19	8/31/19
USA					
<i>American Propeller Redding California</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>6/30/20</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>11/30/18</i>	<i>Not Approved</i>
H & H Propeller Service Inc. Burlington North Carolina	Not Approved	Not Approved	11/30/19	Not Approved	10/31/20
<i>Hartzell Service Center Piqua Ohio</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>9/30/18</i>	<i>9/30/18</i>	<i>Not Approved</i>
<i>Intercontinental Jet Service Tulsa Oklahoma</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>10/31/20</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>10/31/18</i>	<i>Not Approved</i>	<i>10/31/18</i>	<i>3/31/20</i>	<i>Not Approved</i>

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Metal Improvements Co. Grand Prairie Texas	Not Approved	Not Approved	9/30/2020	9/30/20	Not Approved
Metal Improvements Co. Blue Ash Ohio	Approved	Approved	Approved	Approved	Approved
Metal Improvements Co. Miami Florida	6/30/18	8/31/18	6/30/18	Not Approved	Not Approved
Metal Improvements Co. Charlotte North Carolina	Not Approved	Not Approved	5/31/18	Not Approved	Not Approved
Metal Improvements Co. Wellington Kansas	Not Approved	Not Approved	9/30/19	Not Approved	Not Approved
Metal Improvements Co. Addison Illinois	Not Approved	Not Approved	12/31/20	Not Approved	Not Approved
<i>Northwest Propeller Service Puyallup Washington</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>11/30/19</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Ottosen Propeller & Accessories Phoenix Arizona</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>5/31/18</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Palm Beach Aircraft Lantana Florida</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>4/30/18</i>	<i>Not Approved</i>
Precision Propeller Service Boise Idaho	3/31/18	3/31/18	3/31/18	Not Approved	3/31/18
Rocky Mountain Propeller Inc. Erie Colorado	Not Approved	Not Approved	8/31/20	8/31/20	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Texas Aircraft Propeller Pearland Texas	Not Approved	Not Approved	12/31/18	5/31/18	Not Approved
Tiffin Aire Tiffin Ohio	Not Approved	Not Approved	Not Approved	12/31/19	Not Approved
Western Aircraft Propeller Troutdale Oregon	Not Approved	Not Approved	Not Approved	8/31/19	Not Approved