



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>Argentina</b>					
Argenprop S.R.L. Pcia de Buenos Aires	9/30/18	9/30/18	6/30/20	6/30/20	9/30/18
Argentine Air Force Amarilo	Not Approved	*12/31/20	Not Approved	12/31/20	12/31/20
Helices Clerici Buenos Aires	Not Approved	Not Approved	8/31/21	8/31/21	Not Approved
<b>Australia</b>					
<i>East Coast Propellers Pty. Ltd.</i> <i>Sydney New South Wales</i>	<i>6/30/21</i>	<i>Not Approved</i>	<i>8/31/19</i>	<i>Not Approved</i>	<i>Not Approved</i>
Prop Care Australia Pty Ltd. Brisbane Queensland	12/31/20	5/31/21	5/31/21	Not Approved	Not Approved
<b>Brazil</b>					
<i>Diamond Aviação Ltda</i> <i>Goias</i>	Not Approved	*3/31/20	3/31/21	3/31/20	Not Approved
Quick Aviacao Ltda Goias	Not Approved	Not Approved	2/28/2020	2/28/2020	Not Approved
<b>Canada</b>					
<i>Canadian Propeller</i> <i>Winnipeg Manitoba</i>	<i>8/31/20</i>	<i>Not Approved</i>	<i>8/31/2020</i>	<i>Not Approved</i>	<i>Not Approved</i>

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<i>Hope Aero Propeller and Components Inc. Mississauga Ontario</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>2/31/20</i>	<i>11/30/18</i>	<i>Not Approved</i>
Propworks Propeller Systems Inc. Edmonton Alberta	8/31/21	Not Approved	11/30/19	Not Approved	Not Approved
Western Propeller Co. Ltd. Richmond British Columbia	Not Approved	Not Approved	8/31/20	10/31/18	Not Approved
<b>Chile</b>					
Enaer-Empresa Nacional De Aeronautica	Not Approved	Not Approved	Not Approved	7/31/19	Not Approved
<b>China</b>					
Metal Improvement Suzhou Jiangsu	Not Approved	9/30/18	Not Approved	11/30/18	Not Approved
Civil Aviation Flight University of China	Not Approved	Not Approved	Not Approved	1/31/20	Not Approved
Wuhan Hangda Aero ST	Not Approved	Not Approved	Not Approved	4/30/21	Not Approved
<b>France</b>					
<i>Technic Aviation Manosque</i>	<i>4/30/20</i>	<i>*4/30/20</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>
<b>Germany</b>					
<i>Hoffmann GmbH and Co., KG Rosenheim Bavaria</i>	<i>5/31/21</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>5/31/21</i>	<i>Not Approved</i>

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

<b>Company/Location</b>	<b>Aluminum Hub</b>	<b>Steel Hub and Clamps</b>	<b>Blade Surface</b>	<b>Blade Balance Hole</b>	<b>Blade Double Shoulder</b>
Metal Improvements Co. Feuchtwangen North Rhine	Not Approved	Not Approved	2/28/20	2/28/20	Not Approved
MT Propeller GmbH Atting	10/31/19	10/31/19	8/31/20	10/31/19	10/31/19
<b>India</b>					
Arrow Aviation Services Pty Ltd	Not Approved	Not Approved	8/31/20	Not Approved	Not Approved
NSCB Aviation Pvt. Ltd.	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
<b>Italy</b>					
Pubbli Aer Foto Aero Servizi	3/31/19	Not Approved	Not Approved	3/31/19	Not Approved
<b>Japan</b>					
Jamco Corporation	Not Approved	Not Approved	Not Approved	11/30/20	Not Approved
Nicchu Co, LTD	Not Approved	Not Approved	5/31/19	Not Approved	Not Approved
<b>Malaysia</b>					
<b><i>C &amp; A Aviation Ltd.</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>4/30/20</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>
<b>Mexico</b>					
Metal Improvement Company LLC	Not Approved	Not Approved	9/30/2019	Not Approved	Not Approved

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>New Zealand</b>					
<i>Airbus New Zealand Blenheim</i>	<i>5/31/21</i>	<i>5/31/21</i>	<i>5/31/21</i>	<i>6/30/21</i>	<i>Not Approved</i>
<b>Portugal</b>					
Aerohelice LDA Alverca	3/31/19	3/31/19	9/30/18	3/31/19	9/30/18
<b>South Africa</b>					
Joc-Air Pretoria	4/30/21	Not Approved	10/31/19	Not Approved	Not Approved
Visser Import and Export Dynamic Propellers Germiston	Not Approved	Not Approved	8/31/20	Not Approved	Not Approved
<b>Switzerland</b>					
Metal Improvement	Not Approved	Not Approved	4/30/20	Not Approved	Not Approved
RUAG Aviation Lodrino	Not Approved	Not Approved	Not Approved	3/31/19	Not Approved
<b>United Kingdom</b>					
<i>Brinkley Propeller Services LTD Bedfordshire</i>	<i>10/31/20</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Proptech Portsmouth LTD Portsmouth Hampshire</i>	<i>11/30/18</i>	<i>5/31/19</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>Uruguay</b>					
Charles Chalkling S.A. Paysandu-C.P.	Not Approved	Not Approved	6/30/20	8/31/19	8/31/19
<b>USA</b>					
<i>American Propeller Redding California</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>6/30/20</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>11/30/18</i>	<i>Not Approved</i>
H & H Propeller Service Inc. Burlington North Carolina	Not Approved	Not Approved	11/30/19	Not Approved	10/31/20
<i>Hartzell Service Center Piqua Ohio</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>9/30/18</i>	<i>9/30/18</i>	<i>Not Approved</i>
<i>Intercontinental Jet Service Tulsa Oklahoma</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>10/31/20</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>10/31/18</i>	<i>Not Approved</i>	<i>10/31/18</i>	<i>3/31/20</i>	<i>Not Approved</i>
Metal Improvements Co. Grand Prairie Texas	Not Approved	Not Approved	9/30/2020	9/30/20	Not Approved
Metal Improvements Co. Blue Ash Ohio	Approved	Approved	Approved	Approved	Approved
Metal Improvements Co. Miami Florida	6/30/21	8/31/18	6/30/21	Not Approved	Not Approved

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

<b>Company/Location</b>	<b>Aluminum Hub</b>	<b>Steel Hub and Clamps</b>	<b>Blade Surface</b>	<b>Blade Balance Hole</b>	<b>Blade Double Shoulder</b>
Metal Improvements Co. Charlotte North Carolina	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
Metal Improvements Co. Wellington Kansas	Not Approved	Not Approved	9/30/19	Not Approved	Not Approved
Metal Improvements Co. Addison Illinois	Not Approved	Not Approved	12/31/20	Not Approved	Not Approved
<b><i>Northwest Propeller Service Puyallup Washington</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>11/30/19</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>
<b><i>Ottosen Propeller &amp; Accessories Phoenix Arizona</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>
<b><i>Palm Beach Aircraft Lantana Florida</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>Not Approved</i></b>	<b><i>8/31/21</i></b>	<b><i>Not Approved</i></b>
Peening Technologies East Hartford Connecticut	Not Approved	Not Approved	2/28/21	Not Approved	Not Approved
Peening Technologies Austell Georgia	Not Approved	Not Approved	2/28/21	Not Approved	Not Approved
Precision Propeller Service Boise Idaho	4/30/21	4/30/21	4/30/21	Not Approved	4/30/21
Rocky Mountain Propeller Inc. Erie Colorado	Not Approved	Not Approved	8/31/20	8/31/20	Not Approved
Texas Aircraft Propeller Pearland Texas	Not Approved	Not Approved	12/31/18	6/30/21	Not Approved

### Shot Peening Approval Listing

\* Approved for Steel Clamps only



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

<b>Company/Location</b>	<b>Aluminum Hub</b>	<b>Steel Hub and Clamps</b>	<b>Blade Surface</b>	<b>Blade Balance Hole</b>	<b>Blade Double Shoulder</b>
Tiffin Aire Tiffin Ohio	Not Approved	Not Approved	Not Approved	12/31/19	Not Approved
Western Aircraft Propeller Troutdale Oregon	Not Approved	Not Approved	Not Approved	8/31/19	Not Approved