

Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

			iera i tehiereenienie ihhiereeni	
Company/Location Argentina		aul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Helices Clerici Propellers Buenos Aires		Not Approved	2,7	**9/30/32
Australia				
Airbus Group Austra Dingley Vi	alia ctoria	Not Approved	3	**2/28/28
Airflite Pty. Ltd. Perth W	/estern Australia	12/31/26	3,6,7	11/30/31
East Coast Propelle Sydney	ers Pty. Ltd. New South Wales	#4/30/27	1,2,3,7	1/31/33
Prop Care Australia I Brisbane	Pty Ltd. Queensland	Not Approved	None Approved	N/A
Southern Propeller S Salisbury Sc	ervice Pty. Ltd. outh Aistralia	4/30/27	None Approved	N/A
West Coast Propellers Pty. Ltd.		10/31/27	3,7,8	5/31/28
_	estern Australia Composite Bl	ade Overhaul and E	rosion Shield Replacement Approval L # Equipped for Compliance of HC-SE	Listing Page 1 of 8



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing. Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

		····· ··· ··· ···· ···· ··· · · · · ·	
Company/Location <i>Brazil</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Diamond Aviação Ltda Goias	1/31/28	1,2,7,8	7/31/26
Aerotechnica Paulista Servicos Sao Paulo	3/31/24	7,10	8/31/2032
Canada			
AMK Aviation Inc. Murrillo Ontario	3/31/24	5	3/31/28
Canadian Propeller Winnipeg Manitoba	#1/31/28	1,2,3,5,6,7,8,10	10/31/33
Hope Aero Propeller and Compo Mississauga Ontario	onents 6/30/24	2,5,6,7,10	9/30/29
Propworks Propeller Edmonton Alberta	2/28/27	5,7	9/30/29
		None Approved rosion Shield Replacement Approval # Equipped for Compliance of HC-S	E E E E E E E E E E E E E E E E E E E
	· · · · · · · · · · · · · · · · · · ·		- Widi/24



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing. Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Over	haul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Western Propeller C	o. Ltd Pacific	10/31/26	5,6	7/31/30
Richmond	British Columbia			
China				
Shenyang Avias Shenyang		Not Approved	None Approved	N/A
Columbia				
General Propeller S Bogata	ervices SAS	6/30/24	5	6/30/32
Denmark				
ScanAviation Copenhagen		12/31/26	2,5,7,8	1/31/34
France				
Technic Aviation Manosque		2/28/27	3,5,6,7,8	2/28/27

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319

Page 3 of 8 Mar/24



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing. Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

		iola ropiacomont/ipproval.	
Company/Location <i>Germany</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Hoffmann GmbH and Co., KG Rosenheim Bavaria	Not Approved	None Approved	N/A
MT Propeller GmbH Atting	#1/31/28	1,2,4,5,6,7,8,10	9/30/31
Röder Präzision GmbH Egelsbach Hessen	Not Approved	None Approved	N/A
Malaysia			
C & A Aviation Ltd.	6/30/24	2,5,6,7	1/31/2032
Mexico			
ASI Propeller	Not Approved	None Approved	N/A
New Zealand			
Airbus New Zealand Blenheim	Not Approved	2,5	Not Approved
Com	oosite Blade Overhaul and E	rosion Shield Replacement Approval	Listing Date 4 of 9

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

Company/Location <i>Norway</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Norronafly P & P AS Oslo	4/30/27	5,6	Not Approved
Portugal			
Aerohelice LDA Alverca	5/31/26	2,5,7	1/31/33
South Africa			
Dynamic Propeller Germiston	2/28/27	2,5,6,7	8/31/31
Joc-Air Pretoria	5/31/26	1,2,5,6,7,10	7/31/33
Propeller Centre Les Marais Pretoria	2/28/26	2,5,6,7	1/31/26
South Korea			
JCA Autonomous Co. Ltd.	12/31/25	2,7	8/31/32
		rosion Shield Replacement Approval	

* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319

Page 5 of 8 Mar/24



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

		1 11	
Company/Location Switzerland	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Pilatus Aircraft	5/31/26	3,7	5/31/29
United Kingdom			
Brinkley Propeller Servic Nr Shefford Bedfor	es LTD 6/30/24 rdshire	2,7,8,10	5/31/30
Proptech Portsmouth LT Portsmouth Ham	D #6/30/24 pshire	2,3,4,5,6	11/30/24
USA			
American Propeller Servi Redding Calif	ice 10/31/26 Fornia	1,2,5,6,7,8,10	6/30/33
Aircraft Propeller Works Auburndale Florid	3/31/24 da	2,6,7,10	9/30/29
Aviation Propellers Inc. Opa Locka Flori	6/30/24 ida	5,6	11/30/25

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing. Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location		Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Hartzell Service C	Senter	#10/31/24	1,2,3,4,5,6,7,8,9,10	5/31/27
Piqua	Ohio			
Johnson Propeller		1/31/28	None Approved	N/A
Shafter	California			
Jordan Propeller	Service, Inc.	12/31/26	2,6,7	11/30/30
San Antonio	Texas			
InterContinental 、 Oklahoma	Jet	10/31/27	1,2,5,6,7,8,10	1/31/31
Oklanoma				
Maxwell Aircraft S	Service	6/30/24	1,2,5,6,7,8,10	6/30/33
Minneapolis	Minnesota			
New England Prop	eller Service	#6/30/24	1,2,4,5,6,7,8,10	10/31/27
East Haddam	Connecticut			
Northwest Propel	ler Service, In	c. 10/31/26	None Approved	N/A
Puyallup	Washington	n		
Ottosen Propeller		#Not Approved	None Approved	N/A
Phoenix	Arizona			
	Compo	site Blade Overhaul and E	rosion Shield Replacement Approval	Listing

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing * Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319



Hartzell Recommended Service Facilities are listed in bold italic type. For contact information see our Worldwide Service Facilities listing. Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location		Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Piedmont Propuls Winston-Salem	ion Systems, North Caro		2,5,7	5/31/32
Rocky Mountain Pro Erie	opeller Colorado	2/28/27	None Approved	N/A
Sensenich Propelle Gainesville	r Service, Inc. Georgia	6/30/24	None Approved	N/A
Sensenich Propelle Lititz	er Service, Inc. Pennsylvania	6/30/24	2,5,6,7,10	10/31/27
Texas Aircraft Pro		2/28/27	None Approved	N/A
Pearland	Texas			
Tiffin Aire Tiffin	Ohio	#6/30/24	1,2,5,6,7,8,10	10/31/26
Yingling Aircraft Inc Wichita	Kansas	10/31/26	5,7	5/31/31