

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Argentina			
<i>Helices Clerici Propellers Buenos Aires</i>	<i>Not Approved</i>	<i>2,7</i>	<i>**9/30/32</i>
Australia			
Airbus Group Australia Dingley Victoria	Not Approved	3	**2/28/28
Airflite Pty. Ltd. Perth Western Australia	12/31/26	3,6,7	11/30/31
<i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i>	<i>#4/30/27</i>	<i>1,2,3,7,8</i>	<i>5/31/34</i>
Prop Care Australia Pty Ltd. Brisbane Queensland	Not Approved	None Approved	N/A
Southern Propeller Service Pty. Ltd. Salisbury South Aistralia	4/30/27	7	5/31/34
<i>West Coast Propellers Pty. Ltd. Perth Western Australia</i>	<i>10/31/27</i>	<i>3,7,8</i>	<i>5/31/28</i>

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing
* Approved for ASC II Blades Only # Equipped for Compliance of HC-SB-61-319

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Brazil			
<i>Diamond Aviação Ltda</i> <i>Goias</i>	<i>1/31/28</i>	<i>1,2,7,8</i>	<i>7/31/26</i>
Aerotechnica Paulista Servicos Sao Paulo	**Not Approved	7,10	8/31/2032
Canada			
AMK Aviation Inc. Murrillo Ontario	5/31/28	5	3/31/28
<i>Canadian Propeller</i> <i>Winnipeg Manitoba</i>	<i>#1/31/28</i>	<i>1,2,3,5,6,7,8,10</i>	<i>10/31/33</i>
<i>Hope Aero Propeller and Components</i> <i>Mississauga Ontario</i>	<i>6/30/24</i>	<i>2,5,6,7,10</i>	<i>9/30/29</i>
Propworks Propeller Edmonton Alberta	2/28/27	5,7	9/30/29
Propworks Propeller Winnipeg	Not Approved	None Approved	N/A

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

****The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.**

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	10/31/26	5,6	7/31/30
China			
Shenyang Avias Shenyang	Not Approved	None Approved	N/A
Columbia			
General Propeller Services SAS Bogata	Not Approved	5	**6/30/32
Denmark			
ScanAviation Copenhagen	12/31/26	2,5,7,8	1/31/34
France			
Technic Aviation Manosque	2/28/27	3,5,6,7,8	2/28/27

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Germany			
Hoffmann GmbH and Co., KG Rosenheim Bavaria	Not Approved	None Approved	N/A
MT Propeller GmbH Atting	#1/31/28	1,2,4,5,6,7,8,10	9/30/31
Röder Präzision GmbH Egelsbach Hessen	Not Approved	None Approved	N/A
Malaysia			
C & A Aviation Ltd.	12/31/24	2,5,6,7	1/31/2032
Mexico			
ASI Propeller	Not Approved	None Approved	N/A
New Zealand			
Airbus New Zealand Blenheim	Not Approved	2,5	Not Approved

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement Blade Families are listed in the Hartzell Composite Blade Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Norway			
<i>Norronafly P & P AS Oslo</i>	<i>4/30/27</i>	<i>5,6,8</i>	<i>5/31/34</i>
Portugal			
<i>Aerohelice LDA Alverca</i>	<i>5/31/26</i>	<i>2,5,7</i>	<i>1/31/33</i>
South Africa			
<i>Dynamic Propeller Germiston</i>	<i>2/28/27</i>	<i>2,5,6,7</i>	<i>8/31/31</i>
<i>Joc-Air Pretoria</i>	<i>5/31/26</i>	<i>1,2,5,6,7,10</i>	<i>7/31/33</i>
<i>Propeller Centre Les Marais Pretoria</i>	<i>2/28/26</i>	<i>2,5,6,7</i>	<i>1/31/26</i>
South Korea			
<i>JCA Autonomous Co. Ltd.</i>	<i>12/31/25</i>	<i>2,7</i>	<i>8/31/32</i>

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to
hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Switzerland			
Pilatus Aircraft	5/31/26	3,7	5/31/29
United Kingdom			
Brinkley Propeller Services LTD Nr Shefford Bedfordshire	8/31/24	2,7,8,10	5/31/30
Proptech Portsmouth LTD Portsmouth Hampshire	#9/30/24	2,3,4,5,6	11/30/24
USA			
American Propeller Service Redding California	10/31/26	1,2,5,6,7,8,10	6/30/33
Aircraft Propeller Works Auburndale Florida	9/31/24	1,2,6,7,10	5/31/34
Aviation Propellers Inc. Opa Locka Florida	5/31/28	5,6	11/30/25

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Hartzell Service Center Piqua Ohio</i>	<i>#10/31/24</i>	<i>1,2,3,4,5,6,7,8,9,10</i>	<i>5/31/27</i>
Johnson Propeller Shafter California	1/31/28	None Approved	N/A
<i>Jordan Propeller Service, Inc. San Antonio Texas</i>	<i>12/31/26</i>	<i>2,6,7</i>	<i>11/30/30</i>
<i>InterContinental Jet Oklahoma</i>	<i>10/31/27</i>	<i>1,2,5,6,7,8,10</i>	<i>1/31/31</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>12/31/24</i>	<i>1,2,5,6,7,8,10</i>	<i>6/30/33</i>
New England Propeller Service East Haddam Connecticut	#12/31/24	1,2,4,5,6,7,8,10	10/31/27
<i>Northwest Propeller Service, Inc. Puyallup Washington</i>	<i>10/31/26</i>	<i>None Approved</i>	<i>N/A</i>
<i>Ottosen Propeller Phoenix Arizona</i>	<i>#Not Approved</i>	<i>None Approved</i>	<i>N/A</i>

Sample Program Approval Listing

Composite Blade Certifications



Hartzell Recommended Service Facilities are listed in bold italic type.
For contact information see our Worldwide Service Facilities listing.

Erosion Shield Replacement
Blade Families are listed in
the Hartzell Composite Blade
Overhaul Manual 135F.

**The company must have current 4 year recurrent Overhaul/Major repair approval to
hold Erosion Shield Replacement Approval.

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<i>Piedmont Propulsion Systems, LLC.</i> <i>Winston-Salem North Carolina</i>	<i>1/31/28</i>	<i>2,5,7</i>	<i>5/31/32</i>
Rocky Mountain Propeller Erie Colorado	2/28/27	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	Not Approved	None Approved	N/A
Sensenich Propeller Service, Inc. Lititz Pennsylvania	7/31/24	2,5,6,7,8,10	6/30/34
<i>Texas Aircraft Propeller</i> <i>Pearland Texas</i>	<i>2/28/27</i>	<i>None Approved</i>	<i>N/A</i>
Tiffin Aire Tiffin Ohio	#12/31/24	1,2,5,6,7,8,10	10/31/26
Yingling Aircraft Inc. Wichita Kansas	10/31/26	5,7	5/31/31