



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Argentina					
Argenprop S.R.L. Pcia de Buenos Aires	1/31/26	Not Approved	8/31/26	1/31/26	Not Approved
Argentine Air Force Las Higueras	Not Approved	*3/31/2025	Not Approved	3/31/25	3/31/25
Helices Clerici Buenos Aires	Not Approved	Not Approved	7/31/25	7/31/25	Not Approved
Australia					
<i>East Coast Propellers Pty. Ltd.</i> <i>Sydney New South Wales</i>	<i>1/31/25</i>	<i>Not Approved</i>	<i>1/31/25</i>	<i>1/31/25</i>	<i>Not Approved</i>
Prop Care Australia Pty Ltd. Brisbane Queensland	11/30/26	Not Approved	Not Approved	Not Approved	Not Approved
Suncoast Aero Engines	Not Approved	Not Approved	8/31/25	Not Approved	Not Approved
Brazil					
<i>Diamond Aviação Ltda</i> <i>Goias</i>	<i>3/31/26</i>	<i>*3/31/26</i>	<i>3/31/26</i>	<i>3/31/26</i>	Not Approved
Global Parts LTDA	Not Approved	Not Approved	5/31/27	Not Approved	Not Approved
Oficina De Helieces Costa Campo Grande Mato Grosso	Not Approved	Not Approved	9/30/25	Not Approved	Not Approved
Quick Aviacao Ltda Goias	5/31/26	*5/31/26	5/31/26	5/31/26	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Runway Aviation Goias	Not Approved	Not Approved	11/30/26	Not Approved	Not Approved
Serrana Aircraft Maintenance Sao Gabriel	Not Approved	Not Approved	10/31/26	Not Approved	Not Approved
VMF Aeronautica Ltda	Not Approved	Not Approved	4/30/2027	Not Approved	Not Approved
Canada					
<i>Canadian Propeller Winnipeg Manitoba</i>	<i>9/30/26</i>	<i>3/31/27</i>	<i>9/30/26</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Hope Aero Propeller and Components Inc. Mississauga Ontario</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>3/31/26</i>	<i>12/31/24</i>	<i>Not Approved</i>
Propworks Propeller Systems Inc. Edmonton Alberta	8/31/24	*4/30/25	12/31/25	Not Approved	Not Approved
Western Propeller Co. Ltd. Richmond British Columbia	Not Approved	*11/30/24	12/31/26	Not Approved	Not Approved
Chile					
Enaer-Empresa Nacional De Aeronautica	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
China					
Metal Improvement Suzhou Jiangsu	7/31/25	7/31/25	7/31/25	Not Approved	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Civil Aviation Flight University of China	Not Approved	Not Approved	3/31/26	Not Approved	Not Approved
Shenyang Avias Aviation	Not Approved	Not Approved	6/30/26	6/30/26	Not Approved
Wuhan Hangda	Not Approved	Not Approved	Not Approved	8/31/26	Not Approved
Columbia					
Aero-Helices SAS Santa Fe Bogota	Not Approved	Not Approved	10/31/26	Not Approved	Not Approved
Denmark					
Scan Aviation A/S Copenhagen	Not Approved	Not Approved	9/30/26	12/31/26	Not Approved
France					
<i>Technic Aviation Manosque</i>	<i>6/30/24</i>	<i>*6/30/24</i>	<i>4/30/27</i>	<i>8/31/24</i>	<i>Not Approved</i>
Germany					
<i>Hoffmann GmbH and Co., KG Rosenheim Bavaria</i>	<i>7/31/24</i>	<i>Not Approved</i>	<i>11/30/26</i>	<i>7/31/24</i>	<i>Not Approved</i>
MT Propeller GmbH Atting	10/31/25	10/31/25	8/31/26	10/31/25	10/31/25
OSK-Kiefer	Not Approved	Not Approved	8/31/26	Not Approved	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
India					
Arrow Aviation Services Pty Ltd	5/31/25	3/31/26	9/30/26	Not Approved	Not Approved
Hindustan Aeronautics Ltd	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
Indamer Aviation Private Limited	Not Approved	Not Approved	1/31/25	Not Approved	Not Approved
NSCB Aviation Pvt. Ltd.	Not Approved	Not Approved	8/31/24	Not Approved	Not Approved
Italy					
Pubbli Aer Foto Aeroservizi	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
Malaysia					
<i>C & A Aviation Ltd.</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>2/28/27</i>	<i>Not Approved</i>	<i>Not Approved</i>
New Zealand					
<i>Airbus New Zealand Blenheim</i>	<i>6/30/24</i>	<i>6/30/24</i>	<i>6/30/24</i>	<i>6/30/24</i>	<i>Not Approved</i>
Norway					
<i>Norronafly Oslo</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>6/30/24</i>	<i>Not Approved</i>
Philippines					
FIL-OZ Aircraft Propellers	Not Approved	*3/31/26	3/31/26	3/31/26	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
Portugal					
Aerohelice LDA Alverca	4/30/25	4/30/25	11/30/24	4/30/25	11/30/24
South Africa					
Joc-Air Pretoria	5/31/27	Not Approved	7/31/25	7/31/25	Not Approved
Propeller Centre CC Pretoria	Not Approved	Not Approved	Not Approved	1/31/26	Not approved
Visser Import and Export Dynamic Propellers Germiston	Not Approved	Not Approved	8/31/26	Not Approved	Not Approved
Switzerland					
RUAG Aviation Lodrino	Not Approved	Not Approved	12/31/26	12/31/25	Not Approved
United Kingdom					
<i>Brinkley Propeller Services LTD Bedfordshire</i>	<i>10/31/26</i>	<i>Not Approved</i>	<i>10/31/24</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Proptech Portsmouth LTD Portsmouth Hampshire</i>	<i>3/31/25</i>	<i>8/31/25</i>	<i>3/31/25</i>	<i>8/31/25</i>	<i>Not Approved</i>
Uruguay					
Aircraft Repair Station Paysandu-C.P.	Not Approved	Not Approved	7/31/25	7/31/25	7/31/25

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
USA					
<i>American Propeller Redding California</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>7/31/26</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Aviation Propellers Inc. Opa Locka Florida</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>
Byam Propeller Fort Worth Texas	6/30/25	Not Approved	Not Approved	Not Approved	Not Approved
H & H Propeller Service Inc. Burlington North Carolina	Not Approved	Not Approved	9/30/26	Not Approved	10/31/26
<i>Hartzell Service Center Piqua Ohio</i>	<i>HPI</i>	<i>HPI</i>	<i>HPI</i>	<i>HPI</i>	<i>HPI</i>
<i>Intercontinental Jet Service Tulsa Oklahoma</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>10/31/26</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Maxwell Aircraft Service Minneapolis Minnesota</i>	<i>2/28/26</i>	<i>Not Approved</i>	<i>9/30/25</i>	<i>Not Approved</i>	<i>Not Approved</i>
Memphis Propeller Service Mississippi	Not Approved	Not Approved	Not Approved	10/31/25	Not Approved
Metal Improvements Co. Blue Ash Ohio	Approved	Approved	Approved	Approved	Approved
Metal Improvements Co. Miami Florida	6/30/24	3/31/25	6/30/24	Not Approved	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<i>Northwest Propeller Service Puyallup Washington</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>12/31/25</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Ottosen Propeller & Accessories Phoenix Arizona</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>9/30/26</i>	<i>Not Approved</i>	<i>Not Approved</i>
<i>Palm Beach Aircraft Lantana Florida</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>Not Approved</i>	<i>12/31/26</i>	<i>Not Approved</i>
Peening Technologies East Hartford Connecticut	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
Peening Technologies Austell Georgia	Not Approved	2/28/26	Not Approved	Not Approved	Not Approved
Precision Propeller Service Boise Idaho	5/31/24	5/31/24	5/31/24	Not Approved	5/31/24
Rocky Mountain Propeller Inc. Erie Colorado	Not Approved	Not Approved	Not Approved	Not Approved	Not Approved
Texas Aircraft Propeller Pearland Texas	Not Approved	Not Approved	11/30/24	Not Approved	Not Approved
Tiffin Aire Tiffin Ohio	Not Approved	Not Approved	Not Approved	12/31/25	Not Approved
Western Aircraft Propeller Troutdale Oregon	Not Approved	Not Approved	Not Approved	11/30/25	Not Approved
Yingling Aviation Wichita Kansas	Not Approved	Not Approved	1/31/27	Not Approved	Not Approved

Shot Peening Approval Listing
* Approved for Steel Clamps only



Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
-------------------------	---------------------	---------------------------------	--------------------------	-------------------------------	----------------------------------

Shot Peening Approval Listing

* Approved for Steel Clamps only