

**HARTZELL PROPELLER INC.  
NON-AVIATION (MARITIME) SERVICE BULLETIN INDEX  
January 05, 2023**

HM-SB-001	Original	02/13/14	Restamping the hub and blade assemblies on affected Hovercraft propellers with maritime model numbers. Replating affected components with cadmium to meet current production specifications.
HM-SB-002	Original	* 01/05/23	Requires replacement of the pitch change knob brackets on affected propellers.

\* Asterisk at end of service document number indicates documents released at the revision date of this listing or indicates a status change of documents, e.g., obsolete.