

HARTZELL PROPELLER INC.

One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.

HARTZELL

Page 1 of 2

HPB55-MMS

December 6, 2002

**MAINTENANCE MANUAL SUPPLEMENT
FOR
STC SA795CE**

HARTZELL PROPELLERS

ON BEECH 95-55, 95-A55, 95-B55, 95-B55A, 95-B55B AIRCRAFT

LOG OF REVISIONS

<u>Revision Number</u>	<u>Revised Pages</u>	<u>Description of Revision</u>	<u>Date</u>
----------------------------	--------------------------	--------------------------------	-------------

NOTE: All changes are indicated by a black vertical line along the left margin.

HPB55-MMS

December 6, 2002

Chapter 4 Airworthiness Limitations

There are no life-limited components used in the STC installation.

Chapter 5 Time limits / Maintenance checks

Recommended Time-Between-Overhaul (TBO) limits for the STC propeller may be found in Hartzell Service Letter 61.

Chapter 30 Ice and Rain Protection

If optional alcohol anti-ice system is installed on the propellers see Hartzell Manual 115 (Hartzell Owner's Manual).

Chapter 61 Propellers

The STC propeller should be installed in accordance with STC Installation Instructions for STC SA795CE.

Further maintenance information for the propeller may be found in Hartzell Manual 115 (Hartzell Owner's Manual) which is included with the propeller.

Propeller overhaul must be accomplished by an approved Propeller Repair Station.

Chapter 71 Powerplant

No change.