



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ( )7690( ),7890( ),B7421( ),E8190( )
  - 2: N7605(B,K)( ),N( )7893(-)( )
  - 3: E9193( )
  - 4: E13890( )
  - 5: A10460( ),E10950( ),E11990( ),E12902( )
  - 6: M10083( ),LM10585( )+4,M10877( )
  - 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
  - 8: NC8834( ),(J)NC10904( ),JNC10905( ).
  - 9: 108MH92,138MH91
  - 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b>Argentina</b>			
<b><i>Helices Clerici Buenos Aires</i></b>	<b><i>Not Approved</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b>Australia</b>			
<b><i>Airbus Group Australia Dingley Victoria</i></b>	<b><i>2/28/22</i></b>	<b><i>3</i></b>	<b><i>2/28/28</i></b>
<b><i>Airflite Pty. Ltd. Perth Western Australia</i></b>	<b><i>9/30/21</i></b>	<b><i>7</i></b>	<b><i>8/31/28</i></b>
<b><i>East Coast Propellers Pty. Ltd. Sydney New South Wales</i></b>	<b><i>#3/28/22</i></b>	<b><i>1,7</i></b>	<b><i>8/31/27</i></b>
<b><i>Prop Care Australia Pty Ltd. Brisbane Queensland</i></b>	<b><i>9/30/21</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>West Coast Propellers Pty. Ltd. Perth Western Australia</i></b>	<b><i>2/28/22</i></b>	<b><i>3,7,8</i></b>	<b><i>5/31/28</i></b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**  
 1: ( )7690( ),7890( ),B7421( ),E8190( )  
 2: N7605(B,K)( ),N( )7893(-)( )  
 3: E9193( )  
 4: E13890( )  
 5: A10460( ),E10950( ),E11990( ),E12902( )  
 6: M10083( ),LM10585( )+4,M10877( )  
 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),  
 N76MO5C( )X,NC10320( ), NC10245( ).  
 8: NC8834( ),(J)NC10904( ),JNC10905( ).  
 9: 108MH92,138MH91  
 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),  
 76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b>Brazil</b>			
<b><i>Diamond Aviação Ltda</i></b> <b><i>Goias</i></b>	<b><i>3/31/20</i></b>	<b><i>1,2,7,8</i></b>	<b><i>7/31/26</i></b>
<b>Canada</b>			
AMK Aviation Inc. Murrillo Ontario	6/30/20	5	3/31/28
<b><i>Canadian Propeller</i></b> <b><i>Winnipeg Manitoba</i></b>	<b><i>#2/28/21</i></b>	<b><i>2,5,6,7</i></b>	<b><i>11/30/27</i></b>
<b><i>Hope Aero Propeller and Components</i></b> <b><i>Mississauga Ontario</i></b>	<b><i>3/31/20</i></b>	<b><i>2,5,6,7,10</i></b>	<b><i>9/30/29</i></b>
Propworks Propeller Edmonton Alberta	9/30/21	5,7	9/30/29
Propworks Propeller Winnipeg	9/30/22	None Approved	N/A
Wasaya Prop Shop LP Thunder Bay Ontario	4/30/20	5	9/30/21



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

- Blade Families**
- 1: ( )7690( ),7890( ),B7421( ),E8190( )
  - 2: N7605(B,K)( ),N( )7893(-)( )
  - 3: E9193( )
  - 4: E13890( )
  - 5: A10460( ),E10950( ),E11990( ),E12902( )
  - 6: M10083( ),LM10585( )+4,M10877( )
  - 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
  - 8: NC8834( ),(J)NC10904( ),JNC10905( ).
  - 9: 108MH92,138MH91
  - 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Western Propeller Co. Ltd. - Pacific Richmond British Columbia	4/30/20	5,6	7/31/20
<b>China</b>			
Shenyang Avias Shenyang	5/30/20	None Approved	N/A
<b>Columbia</b>			
General Propeller Services SAS Bogata	9/30/23	None Approved	N/A
<b>France</b>			
<b>Technic Aviation Manosque</b>	<b>Not Approved</b>	<b>**(3,5,6,7,8)</b>	<b>**2/28/27</b>
<b>Germany</b>			
<b>Hoffmann GmbH and Co., KG Rosenheim Bavaria</b>	<b>3/31/23</b>	<b>None Approved</b>	<b>N/A</b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),  
N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),  
76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
MT Propeller GmbH Atting	#4/30/20	1,2,4,5,6,7,10	5/31/29
<b><i>Röder Präzision GmbH Egelsbach Hessen</i></b>	<b><i>2/28/22</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>Malaysia</i></b>			
<b><i>C &amp; A Aviation Ltd.</i></b>	<b><i>Not Approved</i></b>	<b><i>**5,6</i></b>	<b><i>**10/31/21</i></b>
<b><i>Mexico</i></b>			
ASI Propeller	12/31/22	None Approved	N/A
<b><i>New Zealand</i></b>			
<b><i>Airbus New Zealand Blenheim</i></b>	<b><i>Not Approved</i></b>	<b><i>** (2,5)</i></b>	<b><i>**7/31/23</i></b>
<b><i>Norway</i></b>			
<b><i>Norronafly P &amp; P AS Oslo</i></b>	<b><i>Not Approved</i></b>	<b><i>** (5,6)</i></b>	<b><i>**11/30/22</i></b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b><i>Portugal</i></b>			
Aerohelice LDA Alverca	Not Approved	**2,5	**12/31/26
<b><i>South Africa</i></b>			
Joc-Air Pretoria	9/30/22	1,2,5,6,7	1/31/29
Propeller Centre Les Marais     Pretoria	2/28/21	2,5,6,7	1/31/26
<b><i>Switzerland</i></b>			
Pilatus Aircraft	9/30/22	3,7	05/31/29
<b><i>United Kingdom</i></b>			
<b><i>Brinkley Propeller Services LTD Nr Shefford     Bedfordshire</i></b>	<b><i>12/31/22</i></b>	<b><i>2,7,8</i></b>	<b><i>8/31/29</i></b>
<b><i>Proptech Portsmouth LTD Portsmouth     Hampshire</i></b>	<b><i>#6/30/20</i></b>	<b><i>2,3,4,5,6</i></b>	<b><i>11/30/24</i></b>

Composite Blade Overhaul and Erosion Shield Replacement Approval Listing

\* Approved for ASC II Blades Only     # Equipped for Compliance of HC-SB-61-319



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location <i>USA</i>	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
Aircraft Propeller Service Inc. Wheeling Illinois	Not Approved	None Approved	N/A
<b><i>American Propeller Service Redding California</i></b>	<b><i>10/31/21</i></b>	<b><i>1,2,5,6,7,8</i></b>	<b><i>3/31/28</i></b>
Aircraft Propeller Works Auburndale Florida	4/30/20	2,6,7,10	9/30/29
<b><i>Aviation Propellers Inc. Opa Locka Florida</i></b>	<b><i>10/31/21</i></b>	<b><i>5,6</i></b>	<b><i>11/30/25</i></b>
Great Lakes Aviation Cheyenne Wyoming	Not Approved	**5,6	**3/31/21
<b><i>Hartzell Service Center Piqua Ohio</i></b>	<b><i>#8/31/20</i></b>	<b><i>1,2,3,4,5,6,7,8,9,10</i></b>	<b><i>5/31/27</i></b>
<b><i>Jordan Propeller Service, Inc. San Antonio Texas</i></b>	<b><i>#2/28/22</i></b>	<b><i>2,7</i></b>	<b><i>11/30/2029</i></b>



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b><i>InterContinental Jet Oklahoma</i></b>	<b><i>2/28/22</i></b>	<b><i>2,5</i></b>	<b><i>3/31/29</i></b>
<b><i>Maxwell Aircraft Service Minneapolis Minnesota</i></b>	<b><i>2/28/23</i></b>	<b><i>1,2,7</i></b>	<b><i>10/31/29</i></b>
New England Propeller Service East Haddam Connecticut	#6/30/20	1,2,4,5,6,7,8,10	10/31/27
<b><i>Northwest Propeller Service, Inc. Puyallup Washington</i></b>	<b><i>2/28/23</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>Ottosen Propeller Phoenix Arizona</i></b>	<b><i>#Not Approved</i></b>	<b><i>None Approved</i></b>	<b><i>N/A</i></b>
<b><i>Piedmont Propulsion Systems, LLC. Winston-Salem North Carolina</i></b>	<b><i>9/30/22</i></b>	<b><i>2,5</i></b>	<b><i>6/30/27</i></b>
Santa Monica Propeller Santa Monica California	Not Approved	None Approved	N/A
Sensenich Propeller Service, Inc. Gainesville Georgia	6/30/20	None Approved	N/A



# Sample Program Approval Listing Composite Blade Certifications

Hartzell Recommended Service Facilities are listed in bold italic type.

For contact information see our Worldwide Service Facilities listing.

\*\*The company must have current 4 year recurrent Overhaul/Major repair approval to hold Erosion Shield Replacement Approval.

### Blade Families

- 1: ( )7690( ),7890( ),B7421( ),E8190( )
- 2: N7605(B,K)( ),N( )7893(-)( )
- 3: E9193( )
- 4: E13890( )
- 5: A10460( ),E10950( ),E11990( ),E12902( )
- 6: M10083( ),LM10585( )+4,M10877( )
- 7: NC9208,N7605C(B,K)( ),N( )8301( ),N( )8302( )-( ),N76MO5C( )X,NC10320( ), NC10245( ).
- 8: NC8834( ),(J)NC10904( ),JNC10905( ).
- 9: 108MH92,138MH91
- 10: ( )75AO1-2( ),L76AO1X( ),78D01( ),H79AO6X( ),76CO3( ).

Company/Location	Overhaul/Major Repair Expiration	Erosion Shield Replacement Approved Blade Families	Erosion Shield Replacement Approval Expiration
<b><i>Sensenich Propeller Service, Inc. Lititz Pennsylvania</i></b>	6/30/20	2,5,6,7,10	None
<b><i>Sullivan Propeller Hayward California</i></b>	Not Approved	None Approved	N/A
<b><i>Texas Aircraft Propeller Pearland Texas</i></b>	12/31/22	None Approved	N/A
<b><i>Tiffin Aire Tiffin Ohio</i></b>	#8/31/20	1,2,5,6,7,8,10	10/31/26
<b><i>Yingling Aircraft Inc. Wichita Kansas</i></b>	12/31/22	None Approved	N/A
<b><i>Venezuela</i></b>			
<b><i>Aero Helices De Venezuela Edo. Miranda</i></b>	5/30/20	None Approved	N/A