

Hartzell Propeller Inc  
One Propeller Place  
Piqua, OH 45356-2634 USA

HP3236IM  
Revision A, September 12, 2001

INSTRUCTIONS FOR INSTALLATION OF A  
HARTZELL HC-F3YR-1ARF/F7693F PROPELLER  
AND C-3570 (P) SPINNER  
ON PIPER PA-28-236 AIRCRAFT

<u>Rev No.</u>	<u>Page No.</u>	<u>Date</u>	<u>Description</u>
Original	Title 1-1	July 30, 2001	Complete manual
A	1	September 12, 2001	Revised spinner weight & balance data

FAA  
APPROVED

*[Signature]*  
SEP 19 2001

CHICAGO AIRCRAFT  
CERTIFICATION OFFICE  
CENTRAL REGION.

*Pgs 1*

FAA Approved \_\_\_\_\_ Date \_\_\_\_\_

HP3236IM  
Revision A, September 12, 2001

INSTRUCTIONS FOR INSTALLATION OF A  
HARTZELL HC-F3YR-1ARF/F7693F PROPELLER  
AND C-3570 (P) SPINNER  
ON PIPER PA-28-236 AIRCRAFT

1. Remove original propeller and spinner.
2. Install new propeller and spinner in accordance with Hartzell Owner's Manual number 115(N) or latest revision.
3. Attach Hartzell Propeller Inc. Airplane Flight Manual Supplement to existing Piper Airplane Flight Manual.
4. Revise weight and balance records to show the removal of the original propeller and spinner (using data provided in the Airplane Flight Manual Equipment List) and the addition of the following equipment at the same moment arms:

	<u>Weight</u>
Propeller, Hartzell HC-F3YR-1ARF/F7693F	75.7 lbs.
Spinner Assembly, Hartzell C-3570(P), Bulkhead	1.9 lbs.
Spinner Assembly, Hartzell C-3570(P), Dome	3.1 lbs.

5. Return aircraft to service with FAA Form 337 reference STC.

FAA Approved \_\_\_\_\_ Date \_\_\_\_\_