

HARTZELL PROPELLER INC.

One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.



March 1, 1999

INSTRUCTIONS FOR INSTALLATION OF A HARTZELL PROPELLER & SPINNER

ON RAYTHEON AIRCRAFT COMPANY (BEECH)

S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C, 36, A36 AIRCRAFT

STC SA785CE

LOG OF REVISIONS

<u>Revision Number</u>	<u>Revised Pages</u>	<u>Description of Revision</u>	<u>Date</u>
----------------------------	--------------------------	--------------------------------	-------------

NOTE: All changes are indicated by a black vertical line along the left margin.

APPROVED

FAA Approved _____ **JUN 17 1999** _____

Date _____

CHICAGO AIRCRAFT
CERTIFICATION OFFICE
CENTRAL REGION

**INSTRUCTIONS FOR INSTALLATION OF A HARTZELL PROPELLER & SPINNER
ON RAYTHEON AIRCRAFT COMPANY (BEECH)
S35, V35, V35A, V35B, 35-C33A, E33A, E33C, F33A, F33C, 36, A36 AIRCRAFT**

STC SA785CE

1. Remove original propeller and spinner.
2. Install new propeller and spinner in accordance with Hartzell Manual 115().
3. Attach STC Airplane Flight Manual Supplement to existing Airplane Flight Manual.
4. Revise weight and balance records to show removal of the original propeller and spinner and addition of the following equipment at the same moment arms:

Weight (lbs)

Propeller, Hartzell, two blade,	BHC-C2YF-1R/8468AR, or, BHC-C2YF-1RF/F8468AR	51 51
---------------------------------	---	----------

Spinner, Hartzell A-2295(P)		5
-----------------------------	--	---

OR,

Propeller, Hartzell, three blade,	PHC-C3YF-1R/8468-6R, or, PHC-C3YF-1R/8468A-6R, or, PHC-C3YF-1RF/F8468A-6R	75 75 75
-----------------------------------	---	----------------

Spinner, Hartzell A-2295-1(P)		5
-------------------------------	--	---

5. Return aircraft to service with FAA Form 337 referencing STC.

FAA Approved _____

Date _____