

HARTZELL PROPELLER INC.

SERVICE CENTER

One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.

HARTZELL

INSTRUCTIONS FOR INSTALLATION OF HARTZELL PROPELLERS,
MODEL PHC-L3YF-1RF/F8468A-6R OR BHC-L2YF-1BF/F8468AR,
ON BEECH MODEL 35-33, 35-A33, 35-B33, 35-C33,
E33, F33, G33, J35, K35, M35, N35, AND P35 AIRPLANES

1. Remove original propeller and spinner.
2. Install new propeller and spinner in accordance with Hartzell owners manual 115(). Follow Beech Service Instruction 0625-248 for proper oil transfer adapter installation when removing Beech or Flottorp propellers (follow oil transfer instructions only, disregarding McCauley installation instructions).
3. If necessary, remove governor and replace with governor type required by this STC. Ensure that the governor being installed is set at the proper RPM limitation for the specific engine model.
4. Attach Hartzell Propeller Inc. Airplane Flight Manual Supplement to existing Beech Owners Manual.
5. Revise weight and balance records to show removal of original propeller and spinner and the addition of the appropriate propeller and spinner as listed on the Airplane Flight Manual Supplement.
6. If necessary, revise weight and balance records to show the removal of original governor and the addition of one of the following:

Woodward	210452	(3.0 lbs. @ +10)
Woodward	V210992	(2.8 lbs. @ +10)
Woodward	A210680	(3.0 lbs. @ +10)
Woodward	A210760	(3.0 lbs. @ +10)
Woodward	D2100-001	(3.0 lbs. @ +10)
Flottorp	IF-1	(5.0 lbs. @ +10)
Garwin	34-825	(5.0 lbs. @ +10)

A
APPROVED
 MAR 31 1995
 CHICAGO AIRCRAFT
 CERTIFICATION DEPT.

7. Return aircraft to service with appropriate logbook entry and FAA Form 337 referring to this STC.

Date MAR 31 1995