



# Sample Program Approval Listing

## Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>Argentina</b>					
A.O.G. SA Cordoba	Vended	Vended	Vended	6/30/2018	Vended
Argenprop S.R.L. Pcia de Buenos Aires	9/30/18	9/30/18	6/30/17	6/30/17	9/30/18
Argentine Air Force Amarillo	Vended	11/30/17	Vended	11/30/17	2/28/2018
<i>Helices Clerici Propellers Buenos Aires</i>	<i>2/28/16</i>	<i>2/28/2016</i>	<i>10/31/17</i>	<i>10/31/17</i>	<i>2/28/2016</i>
<b>Australia</b>					
<i>East Coast Propellers Pty. Ltd. Sydney</i>	<i>7/31/18</i>	<i>Vended</i>	<i>9/30/16</i>	<i>Vended</i>	<i>Vended</i>
Prop Care Australia Pty Ltd. Brisbane	12/31/17	5/31/18	5/31/18	Vended	Vended
<i>Queensland</i>					
<b>Brazil</b>					
Aerotecnica Paulista Servicos Campo Paulo	Vended	Vended	Vended	5/31/17	Vended
<i>Diamond Aviação Ltda Goiás</i>	<i>Vended</i>	<i>3/31/17</i>	<i>2/28/18</i>	<i>3/31/17</i>	<i>Vended</i>
Lider Signature Belo Horizonto	Vended	6/30/17	Vended	Vended	Vended

### Shot Peening Approval Listing

\* Approved for Steel Clamps only

A Vended Process must be sent to an Approved Facility



# Sample Program Approval Listing

## Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Double Shoulder	
Quick Aviacao Ltda Goiania Goias	3/31/16	3/31/16	3/31/16	3/31/16	Vended	
Parque Material Aeronautico Lagao Santa	Vended	Vended	12/31/15	Vended	Vended	
<b>Canada</b>						
<i>Canadian Propeller Winnipeg</i>	<i>6/30/17</i>	<i>Vended</i>	<i>6/31/2017</i>	<i>Vended</i>	<i>Vended</i>	
<i>Hope Aero Propeller and Components Inc. Mississauga</i>	<i>Vended</i>	<i>Vended</i>	<i>2/28/17</i>	<i>11/30/18</i>	<i>Vended</i>	
Propworks Propeller Systems Inc. Edmonton Alberta	6/30/18	*2/28/18	11/30/16	Vended	Vended	
Western Propeller Co. Ltd. Richmond British Columbia	Vended	Vended	5/31/17	10/31/18	Vended	
<b>China</b>						
Metal Improvement Suzhou	1/31/18	9/30/18	1/31/18	11/30/18	Vended	
<b>France</b>						
<i>Technic Aviation Manosque</i>	<i>1/31/17</i>	<i>12/31/17</i>	<i>5/31/18</i>	<i>Not Approved</i>		

### Shot Peening Approval Listing

\* Approved for Steel Clamps only  
A Vended Process must be sent to an Approved Facility



# Sample Program Approval Listing Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>Germany</b>					
<b>Hoffmann GmbH and Co., KG Rosenheim</b>	<b>4/30/18</b>	<b>2/28/17</b>	<b>11/30/17</b>	<b>11/30/17</b>	<b>2/28/17</b>
Metal Improvements Co. Feuchtwangen	Vended		3/28/17	8/31/17	Vended
MT Propeller GmbH Atting	10/31/16	10/31/16	8/31/17	10/31/16	10/31/16
<b>Japan</b>					
Jamco Corporation	Vended		10/31/171	10/31/17	Vended
<b>Malaysia</b>					
<b>C &amp; A Aviation Ltd.</b>	<b>3/31/16</b>	<b>Vended</b>	<b>4/30/17</b>	<b>Vended</b>	<b>Vended</b>
<b>New Zealand</b>					
<b>Safe Air Ltd Blenheim</b>	<b>4/30/18</b>	<b>4/30/18</b>	<b>4/30/18</b>	<b>4/30/18</b>	<b>Vended</b>
<b>Norway</b>					
<b>Norronafly P &amp; PAS Oslo</b>	<b>Vended</b>		<b>Vended</b>	<b>4/30/18</b>	<b>Vended</b>
<b>Portugal</b>					
Aerohelice LDA Alverca	2/28/16	*12/31/15	9/30/18	12/31/15	9/30/18

## Shot Peening Approval Listing

\* Approved for Steel Clamps only

A Vended Process must be sent to an Approved Facility



# Sample Program Approval Listing

## Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade Surface	Blade Balance Hole	Blade Double Shoulder
<b>Singapore</b>					
ST Aerospace Systems Pte Ltd Paya Lebar	Vended		11/30/17		Vended
<b>South Africa</b>					
Joc-Air Pretoria	Vended		10/31/16	Vended	Vended
<b>Switzerland</b>					
RUAG Aviation Lodrino	Vended		Vended	5/31/16	Vended
<b>United Kingdom</b>					
Brinkley Propeller Services LTD Nr Shefford Bedfordshire	9/30/17		Vended	Vended	Vended
<b>Proptech Portsmouth LTD Portsmouth</b>	<b>11/30/18</b>		<b>3/31/18</b>	<b>7/31/18</b>	<b>Vended</b>
<b>Uruguay</b>					
Charles Chalking S.A. Paysandu-C.P.	Vended		7/31/2017	10/31/16	10/31/16
<b>USA</b>					
American Propeller Redding	Vended		8/31/2016	Vended	Vended

**Shot Peening Approval Listing**  
\* Approved for Steel Clamps only  
A Vended Process must be sent to an Approved Facility



# Sample Program Approval Listing

## Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub <i>Vended</i>	Steel Hub and Clamps <i>Vended</i>	Blade Surface <i>Vended</i>	Blade Balance Hole <i>Vended</i>	Blade Double Shoulder <i>Vended</i>
<b><i>Aviation Propellers Inc.</i></b> <b><i>Opa Locka Florida</i></b>					
H & H Propeller Service Inc. Burlington North Carolina	Vended	Vended	11/30/16	Vended	Vended
<b><i>Hartzell Service Center</i></b> <b><i>Piqua Ohio</i></b>		<b><i>Vended</i></b>	<b><i>9/30/18</i></b>	<b><i>9/30/18</i></b>	<b><i>Vended</i></b>
<b><i>Maxwell Aircraft Service</i></b> <b><i>Minneapolis Minnesota</i></b>	<b><i>10/31/18</i></b>	<b><i>Vended</i></b>	<b><i>10/31/18</i></b>	<b><i>Vended</i></b>	<b><i>Vended</i></b>
Metal Improvements Co. Blue Ash Ohio	Approved	Approved	Approved	Approved	Approved
Metal Improvements Co. Miami Florida	6/30/18	8/31/18	6/30/18	Vended	Vended
Metal Improvements Co. Charlotte North Carolina	Vended	Vended	5/31/18	Vended	Vended
<b><i>Ottosen Propeller &amp; Accessories Inc.</i></b> <b><i>Phoenix Arizona</i></b>		<b><i>Vended</i></b>	<b><i>5/31/18</i></b>	<b><i>Vended</i></b>	<b><i>Vended</i></b>
Palm Beach Aircraft Lantana Florida	Vended	Vended	Vended	4/30/18	Vended
Precision Propeller Service Boise Idaho	3/31/18	3/31/18	3/31/18	Vended	3/31/18
R & D Propeller Service, Inc. Pearland Texas	Vended	Vended	Vended	5/31/18	Vended

### Shot Peening Approval Listing

\* Approved for Steel Clamps only

A Vended Process must be sent to an Approved Facility



# Sample Program Approval Listing

## Shot Peening

Hartzell Recommended Service Facilities are listed in bold italic type.  
For contact information see our Worldwide Service Facilities listing.

Company/Location	Aluminum Hub	Steel Hub and Clamps	Blade	Balance Hole	Blade Double Shoulder
Rocky Mountain Propeller Inc. Erie Colorado	Vended	Vended 7/31/17	Vended 7/31/17	Vended	Vended
Tiffin Aire Tiffin Ohio	Vended	Vended	Vended 12/31/16	Vended	Vended
Western Aircraft Propeller Troutdale Oregon	Vended	Vended	Vended 5/31/16	Vended	Vended

### Shot Peening Approval Listing

\* Approved for Steel Clamps only  
A Vended Process must be sent to an Approved Facility