

HPC112-MMS

January 2, 2002

MAINTENANCE MANUAL SUPPLEMENT  
FOR  
STC SA00499SE

HARTZELL HC-E3YR-1RF/F7392 PROPELLER  
AND C-3535-1(P) SPINNER  
ON ROCKWELL / COMMANDER AIRCRAFT MODEL 112, 112B, 112TC, 112TCA

LOG OF REVISIONS

<u>Revision Number</u>	<u>Revised Pages</u>	<u>Description of Revision</u>	<u>Date</u>
----------------------------	--------------------------	--------------------------------	-------------

NOTE: All changes are indicated by a black vertical line along the left margin.

HPC112-MMS

January 2, 2002

**Chapter 4 Airworthiness Limitations**

There are no life-limited components used in the STC installation.

**Chapter 5 Time limits / Maintenance checks**

Recommended Time-Between-Overhaul (TBO) limits for the STC propeller may be found in Hartzell Service Letter 61.

**Chapter 30 Ice and Rain Protection**

Not applicable; no change.

**Chapter 61 Propellers**

The STC propeller should be installed in accordance with STC Installation Instruction HPC112-1.

Further maintenance information for the propeller may be found in Hartzell Manual 115 (Hartzell Owner's Manual) which is included with the propeller.

Propeller overhaul must be accomplished by an approved Propeller Repair Station.

**Chapter 71 Powerplant**

No change.