Hartzell Propeller, Inc One Propeller Place Piqua OH 45356-2634

HP3235IM

INSTRUCTIONS FOR INSTALLATION OF A

HARTZELL HC-C3YR-1RF/F7693F PROPELLER

AND C-3535-1(P) SPINNER

ON PIPER PA-28-235 AIRCRAFT

Rev No.	Page No.	<u>Date</u>	<u>Discription</u>
Origional	Title 1-1	July 30, 2001	Complete manual

FAA Approved R. Pesuil	Date	aug.	13,200
------------------------	------	------	--------

HP3235IM

INSTRUCTIONS FOR INSTALLATION OF A

HARTZELL HC-C3YR-1RF/F7693F PROPELLER

AND C-3535-1(P) SPINNER

ON PIPER PA-28-235 AIRCRAFT

- 1. Remove original propeller and spinner.
- 2. Install new propeller and spinner in accordance with Hartzell Owner's Manual number 115(N) or latest revision.
- 3. Attach Hartzell Propeller Inc. Airplane Flight Manual Supplement to existing Piper Airplane Flight Manual.
- 4. Revise weight and balance records to show the removal of the original propeller and spinner (using data provided in the Airplane Flight Manual Equipment List) and the addition of the following equipment at the same moment arm:

	Weight
Propeller, Hartzell (Pounds)	
(HC-C3YR-1RF/F7693F)	73
+	
Spinner, Hartzell	
(C-3535-1(P))	4.5

5. Return aircraft to service with FAA Form 337 referencing STC.

FAA Approved R. Pesuit Date Aug. 13, 2001